Martin's of Philadelphia
7327 STATE ROAD
PHILADELPHIA, PA 19136
215-DE1-5565

Specialists in Metal Finishing and Plating

SOLD TO [redacted]
missions
st Rd. Rt 1
02420

INVOICE #
ORDER DATE 1/24/90
E.T.C. 4 wks.
MAKE & YEAR
PHONE # HM.
PHONE # 203-878-5735 WK.
TERMS

ITEM	QUAN.	DESCRIPTION	PRICE EACH	AMOUNT	REPAIR COST
1	4	Bumper Sections (Repair)	135+	540 00	
2					
3					
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					

APPROVED

565 00
CK 316 2/17/90 BAL -0-

125

CUSTOMERS FOLLOW-UP

1/24/90 Repairs #125 00 Marty Baker (2 Checks.
CK 309 1/31/90

GROSS AMOUNT	540 00	+ TOTAL
DEPOSIT	665 00	PARTS TOTAL
MISC. DEDUCTIONS		GRAND TOTAL
BALANCE		

"POT METAL" IS EXTREMELY POROUS AND SUSCEPTIBLE TO EROSION AND CORROSION. THIS CANCER-LIKE CONDITION IS WHY NO GUARANTEE'S ARE EXTENDED.
REPAIR COSTS ARE SEPARATE AND ARE MORE ACCURATELY DETERMINED AFTER PARTS ARE STRIPPED AND BASE METAL IS EXPOSED.

AZTEC'S SOUND'S CONNECTION



SALES & WHOLESALE
CAR STEREO &
TV and VCR Repair

VISA
MasterCard

1209 E. Rosecrans Blvd. Compton, CA 90221

T[redacted] Fax: (310) 763-2425

NAME	PHONE	DATE
	951 775-16	9/15/11
ADDRES		
CITY	TATE	ZIP

SOLD BY	CASH	CHECK #	CHARGE	ON ACCT.	MDSE RETD	PAID OUT
	✓					

QTY.	DESCRIPTION	INST.	PRICE	AMOUNT
	Stereo			
	Amplifier			
	Speakers			
	Labor Only			
	Carry Out			
	Sony 6½ speakers XS GTF 1626			$140
	Alpine tweeters SPS-1005			$60
			PARTS	
			LABOR	
			SUB TOTAL	
			TAX	
			TOTAL	$100

No Refunds on Merchandise Exchange Only Within 30 Days of Purchase With Sales Slip.

No Refunds or Exchange on Any Type of Speakers

60 Days Warranty on Repairs, No Refunds on Any Repairs. Items After 60 Days if Not Pick -up Will Be Lost.

X _____

PRINTED BY NSP: (562) 929-0541

BODY SHOP SUPPLY INC.
(619) 464-4131
7473 BROADWAY
LEMON GROVE, CA 91945-1603

INVOICE

Shop

Bill To:
* * * * CASH * * * * - 1
* * * TAXABLE * * *
CA

Ship To:
Same As Customer Information

Printed: 10/15/2009 11:12:45 AM

INVOICE NUMBER	INVOICE DATE	SLSM CODE	PURCHASE ORDER NUMBER	TAX CODE	TERMS		ORDER NUMBER	SHIP VIA	COUNTER CODE
174219	10/15/2009	5		1	* * C A S H * *	1		Delivery	44

H M	ITEM NUMBER	ITEM DESCRIPTION	T	ORDERED	SHIPPED	UNIT		NET	TOTAL
X	MMM 5954	SUPER DUTY COMPOUND QT	T	2	2	QT		19.12	38.24

PAYMENT DETAILS

Description	Name	Number	Exp Date	Authorization	ID Number	Amount
Cash						100.00
Cash						-58.41

SUB TOTAL:	38.24
CALIFORNIA SALES TAX:	3.35
TOTAL DUE:	41.59
TOTAL PAID:	100.00
BALANCE DUE:	0.00
CHANGE:	58.41

PROPOSITION 65 WARNING: THESE PRODUCTS MAY CONTAIN CHEMICALS KNOWN TO THE STATE OF CALIFORNIA TO CAUSE CANCER, BIRTH DEFECTS, OR OTHER REPRODUCTIVE HARM. CHECK ITEMS FOR RULE 67.20 COMPLIANCE.

Emergency Response Contact: (800) 424-9300 (CHEMTREC),

HM	Hazardous Material Description	#Pks	Unit		Total Wt.
X	BUFFING OR CLEANING COMPOUND, NOI,	2	QT		0
				TOTAL	0

Total Taxable: $38.24

TOTAL DUE: $0.00

Total Auto Repair

ALL TYPES OF CARS

1471 Morena Blvd., San Diego CA 92110
Phone: (619) 276-1049

Bar Registration # **ARD258851** Smog Station # **RC258851**

No. 0884

* CODE N - NEW U - USED R - REBUILT

DA
NA
AD
CI
IONE HOME
WORK
PHILLIP
LOCW RD
TATE CD
ZIP CODE 92024
MAKE INTERNATIONAL
MODEL 1000

QTY.	*	PART NO. OR DESCRIPTION	SALE AMOUNT
1	R	window elevator	125 00
		TOTAL PARTS	125 00

YEAR 1974
ODOMETER

ENG. SIZE	TRANS	VEHICLE TYPE	NUMBER OF CYLINDER	GVW
318	AUT	Coupe	V8	

The dealer named above is authorized by me to perform Smog Control Inspection as required by Article 5 5 of the California Motor Vehicle Inspection Program. The dealer is authorized to operate the vehicle for inspection testing and delivery purposes at the vehicle owner's risk. The cost of performing required inspection services has been explained to my satisfaction. I understand I am liable for costs up to the estimated amount shown whether the vehicle qualities for certification or not.

Customer acknowledges receipt of a copy hereof.

CUST SIGN X _____

TERMS: STRICLY CASH UNLESS OTHER ARRANGEMENTS ARE MADE

ORIGINAL ESTIMATE $ ☐ INSPECTION AND TEST $ ☐ CERTIFICATE $

COST LIMIT MAY NOT APPLY IF THE REQUIRED MOTOR VEHICLE POLLUTION CONTROL DEVICE IS MODIFIED DISCONNECT OR MISSING AS DEFINED BY THE CALIFORNIA VEHICLE CODE SECTION 27156

By law, you may choose another Licensed Smog Check facility to perform any needed repairs or adjustments wich the Smog Check test indicates are necessary.

Revised Estimate 1. $	DATE	BY
Revised Estimate 2. $	DATE	BY

I acknowledge notice and oral approval of an increase in the original estimate

CUST SIGN X _____

REPAIR ORDER - LABOR INSTRUCTIONS

Certificate #

Replace Head lamp elevator 45

Resale # TH100-547313

VISUAL	P	M	N	D	S	WE RECOMMEND THE FOLLOWING REPAIRS
PCV						
TAC						
FEC						
CAT						
EGR						
ISC						
CARB						
FI						
AIR						
O2						
VAC/S						
OTH						
RET						

FUNCTION		
	EWL	
	TIMING	
	EGR	
	FPR	P F N/A

TEST TYPE	PASS	FAIL	ABORT
INITAL			
AFTER REPAIR			

ESTIMATE AMOUNT - FOR PARTS AND LABOR

ADDITIONAL AUTHORIZED AMOUNT	DATE	TIME	DIRECT PHONE	INITIAL	AMOUNT
ADDITIONAL AUTHORIZED AMOUNT			DIRECT PHONE		
ADDITIONAL AUTHORIZED AMOUNT			DIRECT PHONE		
ESTIMATE TOTAL ▶					

TOTAL ORIGINAL ESTIMATE INCLUDING HAZARDOUS WASTE DISPOSAL FEE

DATE

I hereby authorize the repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle herein described on the streets, highways or elsewhere for the purpose of testing and/or inspection. I also authorize any sublet repair that you deem necessary. SUBJECT TO CONDITIONS ON REVERSE SIDE. TERMS: CASH UNLESS OTHER ARRANGMENTS ARE MADE.

CUSTOMER ACJNOWLEDGES RECEIPT HEREOF.

X _____
CUSTOMER SIGNATURE

TOTAL LABOR	45 00
PARTS	125 00
SMOG TEST $ INSPECT FEE	
SMOG CERTIFICATE FEE	
SALES TAX	
SUBLET REPAIR	
PLEASE PAY THIS AMOUNT	170 00

PINK: STIMATE COPY
CANARY: INVOICE COPY
WHITE: OFFICE COPY

WE GUARANTEE OUR LABOR 90 DAYS OR 3000 MILES
GUARANTEE VALID ONLY IF RETURNED TO OUR SERV

Total Auto Repair

ALL TYPES OF CARS

1471 Morena Blvd., San Diego CA 92110
Phone: (619) 276-1049

Bar Registration # **ARD258851** Smog Station # **RC258851**

Certificate [illegible] № 0711

* CODE N - NEW U - USED R - REBUILT

QTY.	*	PART NO. OR DESCRIPTION	SALE AMOUNT
1	D	TRIM Adhesive	14 48
1	D	GROMMET ASSEMBLY	5 42
2	D	EXHAUST WRAP	66 48
4	D	FUEL PUMP FITTINGS	20 88
4	D	FUEL FILTER FITTINGS	46 24
1	D	THERMOSHIELD TAPE	14 95
1	D	FUEL FILTER ASSEMBLY	29 95
1	D	FUEL PUMP RELAY	32 95
1	D	FUEL LINE HOSE	1 99
4	D	COLLAPSABLE WASHERS	4 03
2	D	COLLAPSABLE WASHERS	3 85
1	D	FUEL REGULATOR REBUILT KIT	9 95
2	D	SEAT FOAM PIECE	57 91
1	D	BOOT BRAKE LEVER	11 80
1	D	SPECTY WING	3 95
1	D	WINDSHIELD WIPER DRM	6 00
		TOTAL PARTS	

VISUAL	P	M	N	D	S	WE RECOMMEND THE FOLLOWING REPAIRS
PCV						HOSE PARTS
TAC						FILTER BUTTERFLY 5.49
FEC						WINDSHIELD WIPER
CAT						BLADES 19.04
EGR						
ISC						TOTAL PARTS 462.57
CARB						
FI						
AIR						
O2						
VAC/S						
OTH						
RET						

FUNCTION				
	EWL			
	TIMING			
	EGR			
	FPR	P	F	N/A

TEST TYPE	PASS	FAIL	ABORT
INITAL			
AFTER REPAIR			

ESTIMATE AMOUNT - FOR PARTS AND LABOR

ADDITIONAL AUTHORIZED AMOUNT	DATE	TIME	DIRECT PHONE	INITIAL	AMOUNT
ADDITIONAL AUTHORIZED AMOUNT			DIRECT PHONE		
ADDITIONAL AUTHORIZED AMOUNT			DIRECT PHONE		
ESTIMATE TOTAL ▶					

TOTAL ORIGINAL ESTIMATE INCLUDING HAZARDOUS WASTE DISPOSAL FEE

DATE

I hereby authorize the repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle herein described on the streets, highways or elsewhere for the purpose of testing and/or inspection. I also authorize any sublet repair that you deem necessary. SUBJECT TO CONDITIONS ON REVERSE SIDE. TERMS: CASH UNLESS OTHER ARRANGMENTS ARE MADE.

CUSTOMER ACKNOWLEDGES RECEIPT HEREOF.

X _____
CUSTOMER SIGNATURE

TOTAL LABOR	910	00
PARTS	462	57
SMOG TEST $ INSPECT FEE		
SMOG CERTIFICATE FEE		
SALES TAX		
SUBLET REPAIR		
PLEASE PAY THIS AMOUNT	$ 1372	57

WE GUARANTEE OUR LABOR 90 DAYS OR 3000 MILES
GUARANTEE VALID ONLY IF RETURNED TO OUR SERV

WORK

CCJOE

ZD

ZIP CODE 92024

MODEL 1NDRD

YEAR 1974

ODOMETER

ENG. SIZE	TRANS	VEHICLE TYPE	NUMBER OF CYLINDER	GVW
LT1	AUT	COUPE	V8	

The dealer named above is authorized by me to perform Smog Control Inspection as required by Article 5 5 of the California Motor Vehicle Inspection Program. The dealer is authorized to operate the vehicle for inspection testing and delivery purposes at the vehicle owner's risk. The cost of performing required inspection services has been explained to my satisfaction. I understand I am liable for costs up to the estimated amount shown whether the vehicle qualities for certification or not.

Customer acknowledges receipt of a copy hereof.

CUST SIGN X _____

TERMS: STRICLY CASH UNLESS OTHER ARRANGEMENTS ARE MADE

By law, you may choose another Licensed Smog Check facility to perform any needed repairs or adjustments wich the Smog Check test indicates are necessary.

Revised Estimate 1. $	DATE	BY
Revised Estimate 2. $	DATE	BY

ORIGINAL ESTIMATE $ ☐ INSPECTION AND TEST $ ☐ CERTIFICATE $

COST LIMIT MAY NOT APPLY IF THE REQUIRED MOTOR VEHICLE POLLUTION CONTROL DEVICE IS MODIFIED DISCONNECT OR MISSING AS DEFINED BY THE CALIFORNIA VEHICLE CODE SECTION 27156

I acknowledge notice and oral approval of an increase in the original estimate

CUST SIGN X _____

REPAIR ORDER - LABOR INSTRUCTIONS

Certificate #

Replace stereo (1)
Replace and Adapt Fuel pump/Filter (4)
INSULATE EXHAUST (4)
Adapt Brake Boot (1)
Repair Brake Proportioning Valve/Bleed (3)
INSULATE FLOORS (6)
Fill with New Foam Front Seats (3)
Repair Fuel Regulator (1) 3S/HR
Adapt windshield wiper DRMR (1)
Repair Powersteering leak (1)

PINK: STIMATE COPY
CANARY: INVOICE COPY
WHITE: OFFICE COPY

Total Auto Repair

ALL TYPES OF CARS

1471 Morena Blvd., San Diego CA 92110
Phone: (619) 276-1049

Bar Registration # **ARD258851** Smog Station # **RC258851**

No. 1525

DATE

NAME

ADDRESS

CITY

* CODE N - NEW U - USED R - REBUILT

QTY.	*	PART NO. OR DESCRIPTION	SALE AMOUNT
1		WATER PUMP PULLEY	40 00
		TOTAL PARTS	40 00

YEAR 64 LICE

ODOMETER 62

ENG. SIZE	TRANS	VEHICLE TYPE	NUMBER OF CYLINDER	GVW
4	MOT	COUPE	8	

The dealer named above is authorized by me to perform Smog Control Inspection as required by Article 5 5 of the California Motor Vehicle Inspection Program. The dealer is authorized to operate the vehicle for inspection testing and delivery purposes at the vehicle owner's risk. The cost of performing required inspection services has been explained to my satisfaction. I understand I am liable for costs up to the estimated amount shown whether the vehicle qualities for certification or not.

Customer acknowledges receipt of a copy hereof.

CUST SIGN X _____

TERMS: STRICLY CASH UNLESS OTHER ARRANGEMENTS ARE MADE

ORIGINAL ESTIMATE $ ☐ INSPECTION AND TEST $ ☐ CERTIFICATE $

COST LIMIT MAY NOT APPLY IF THE REQUIRED MOTOR VEHICLE POLLUTION CONTROL DEVICE IS MODIFIED DISCONNECT OR MISSING AS DEFINED BY THE CALIFORNIA VEHICLE CODE SECTION 27156

By law, you may choose another Licensed Smog Check facility to perform any needed repairs or adjustments wich the Smog Check test indicates are necessary.

Revised Estimate 1. $	DATE	BY
Revised Estimate 2. $	DATE	BY

I acknowledge notice and oral approval of an increase in the original estimate

CUST SIGN X _____

REPAIR ORDER - LABOR INSTRUCTIONS

Certificate #

Remove Bad Install Carburator 70
Repair Headlamp System 40

VISUAL	P	M	N	D	S
PCV					
TAC					
FEC					
CAT					
EGR					
ISC					
CARB					
FI					
AIR					
O2					
VAC/S					
OTH					
RET					

WE RECOMMEND THE FOLLOWING REPAIRS

FUNCTION		P	F	N/A
	EWL			
	TIMING			
	EGR			
	FPR			

TEST TYPE	PASS	FAIL	ABORT
INITAL			
AFTER REPAIR			

ESTIMATE AMOUNT - FOR PARTS AND LABOR

	DATE	TIME	DIRECT PHONE	INITIAL	AMOUNT
ADDITIONAL AUTHORIZED AMOUNT					
ADDITIONAL AUTHORIZED AMOUNT			DIRECT PHONE		
ADDITIONAL AUTHORIZED AMOUNT			DIRECT PHONE		
ESTIMATE TOTAL ▶					

TOTAL ORIGINAL ESTIMATE INCLUDING HAZARDOUS WASTE DISPOSAL FEE

DATE

I hereby authorize the repair work to be done along with the necessary material, and hereby grant you and/or your employees permission to operate the vehicle herein described on the streets, highways or elsewhere for the purpose of testing and/or inspection. I also authorize any sublet repair that you deem necessary. SUBJECT TO CONDITIONS ON REVERSE SIDE. TERMS: CASH UNLESS OTHER ARRANGMENTS ARE MADE.

CUSTOMER ACJNOWLEDGES RECEIPT HEREOF.

X _____ CUSTOMER SIGNATURE

TOTAL LABOR	110 00
PARTS	40 00
SMOG TEST $ INSPECT FEE	
SMOG CERTIFICATE FEE	3
SALES TAX	3 50
SUBLET REPAIR	
PLEASE PAY THIS AMOUNT	153 50

PINK: STIMATE COPY

CANARY: INVOICE COPY

WHITE: OFFICE COPY

WE GUARANTEE OUR LABOR 90 DAYS OR 3000 MILES
GUARANTEE VALID ONLY IF RETURNED TO OUR SERV

JACK'S AUTOMOTIVE CREATIONS

INVOICE

(619)405-0675

DATE: AUGUST 13, 2009

TO

[PH

od

FOR:
[Project or service description]
1974 Intermeccanica INDRA 2+2 327cid.
Car won't run, and overheated when drove last.

Car was pushed in not running. 16JULY09

DESCRIPTION	Labor $40hr	Sublet	AMOUNT
Found no fuel getting carb. Removed fuel pump and cleaned, replaced all rubber fuel lines, (cracked). Still no fuel. Drained all old fuel from gas tank and disposed of fuel, removed gas tank from car. Found pick up tube not at bottom of tank and cracked where entering fuel tank. Washed out fuel tank with soap and water then acid washed and dried. Cut old pickup tube from gas tank, fabricated new pickup tube and welded to gas tank. Installed new fuel filter. Tested for leaks and reinstalled tank into car, filled with new 91 octane fuel. Car now runs. Drained and flushed coolant from engine and coolant system, (100% antifreeze). Removed thermostat and **found** 195 deg. To hot for this application. Also **found** radiator plugged up from front and debris in tank. Removed radiator and sent to shop for cleaning and repairs. Installed New 180 deg. High Flow Thermostat & new Thermostat Housing. Replaced water pump with New Heavy Duty pump, (special order). Relocated Temp. sensor to better location on engine for accurate reading. Straightened radiator support bracket back to proper location, found radiator pushed up into hood. Installed repaired and painted radiator, back into car with new 50/50 prestone antifreeze. Bled coolant system and tested. Replaced Thermo Fan Clutch, old one not locking up. Needs new battery, won't hold a charge overnight. Purchased new battery and installed. Rewired power shut-off to working condition. Replaced all belts and painted Alternator brackets. Cleaned & repainted Engine and polish Valve Covers (removed carb. and other acc). Replaced Exhaust Manifold gaskets & exhaust donuts both sides, welded exhaust bracket.	33.5 hrs		$1340.0
Parts: Hard fuel line $10.20 Fuel hose $ 6.57 New Thermostat housing $15.40 2 gal antifreeze $21.98 Battery $87.99 2 cans paint $ 12.08 Exhaust Gaskets $ 21.98 Valve Cover Gaskets $ 14.00 Fuel filter $4.70 Thermostat & gasket $16.48 New water pump w/shipping $ 150.00 Fan clutch $ 86.33 Repaired radiator $ 145.00 Gasoline $34.00 New Belts (3) $ 40.00			$666.71
Labor			$1340.0
Parts			$666.71
Tax			$58.43
Customers Copy	**TOTAL**		$2065.14

Thank you for your business!

JACK'S AUTOMOTIVE CREATIONS

INVOICE

(619)405-0675

DATE: AUGUST 17, 2009

FOR:
[Project or service description]
1974 Intermeccanica INDRA 2+2 327cid.
Car won't run, and overheated when drove last.

Car was pushed in not running. 16JULY09

DESCRIPTION	Labor $40hr	Sublet	AMOUNT
Found no fuel getting carb. Removed fuel pump and cleaned, replaced all rubber fuel lines, (cracked). Still no fuel. Drained all old fuel from gas tank and disposed of fuel, removed gas tank from car. Found pick up tube not at bottom of tank and cracked where entering fuel tank. Washed out fuel tank with soap and water then acid washed and dried. Cut old pickup tube from gas tank, fabricated new pickup tube and welded to gas tank. Installed new fuel filter. Tested for leaks and reinstalled tank into car, filled with new 91 octane fuel. Car now runs. REPAIRED FUEL TANK SENDING UNIT, now working. Drained and flushed coolant from engine and coolant system, (100% antifreeze). Removed thermostat and **found** 195 deg. To hot for this application. Also **found** radiator plugged up from front and debris in tank. Removed radiator and sent to shop for cleaning and repairs. Installed New 180 deg. High Flow Thermostat & new Thermostat Housing. Replaced water pump with New Heavy Duty pump, (special order). Relocated Temp. sensor to better location on engine for accurate reading. Straightened radiator support bracket back to proper location, found radiator pushed up into hood. Installed repaired and painted radiator, back into car with new 50/50 prestone antifreeze. Bled coolant system and tested. Replaced Thermo Fan Clutch, old one not locking up. Needs new battery, won't hold a charge overnight. Purchased new battery and installed. Rewired power shut-off to working condition. Replaced all belts and painted Alternator brackets. Cleaned & repainted Engine and polish Valve Covers (removed carb. and other acc). Replaced Exhaust Manifold gaskets & exhaust donuts both sides, welded exhaust bracket.	33.5 hrs		$1340.0 ~~990~~ 1003
Parts: Hard fuel line $10.20 Fuel hose $ 6.57 New Thermostat housing $15.40 2 gal antifreeze $21.98 Battery $87.99 2 cans paint $ 12.08 Exhaust Gaskets $ 21.98 Valve Cover Gaskets $ 14.00 Fuel filter $4.70 Thermostat & gasket $16.48 New water pump w/shipping $ 150.00 Fan clutch $ 86.33 Repaired radiator $ 145.00 Gasoline $34.00 New Belts (3) $ 40.00			$666.71
Labor			$1340.0
Parts			$666.71
Tax			$58.43
	TOTAL		2065.14 ~~2065.14~~

Thank you for your business!

1730
400
1330

T.P AUTO REPAIR
2426 El Cajon Blvd
San Diego, Ca. 92104
Phone - 619-299-6966
Napa AutoCare Center

INVOICE
25291
Org. Est. # 012869
BAR # AH 217832
EPA # CAL000203212

Print Date : 03/20/2008

1974 InterMECCANICA - INDRA
LT1 CHEVY V-8
Lic # :
Unit # :
Vin # : **10002419**
Hat # :
Odometer In : 5805

619-699-3992
Ref # :

Part Description / Number	Qty	Sale	Extended
ENGINE OIL			
N	5.00		
OIL FILTER			
N	1.00		
ANTI-FREEZE COOLANT			
n	1.00		
AUTO. TRANS. FLUID			
N	7.00		
THERMOSTAT			
N	1.00	12.00	12.00

Labor Description	Extended
OIL CHANGE AND FILTER	N/C
COOLANT FLUSH	N/C
TRANSMISSION FLUID FLUSH	N/C
INSTALL THERMOSTAT	45.00

[Technicians : Tran , Tuong]

Org. Estimate $57.93 Revisions $0.00 Current Estimate $ 57.93 Additional Cost Revised Estimate

Labor:	**45.00**
Parts:	**12.00**
Sublet:	**0.00**
Sub:	**57.00**
Tax:	**0.93**
Total:	**57.93**
Bal Due:	**$57.93**

[Payments -]

Serving You Since 1986

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is 90 days or 3,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

SIGNATURE..... Date..... Time.....

Written By: Nguyen, Phong

01.17.07 Copyright Mitchell 1 Invoic1

ALTERNATIVE SOURCE AUTOMOTIVE BUSINESS FORMS, INC. (800) 495-8855 • (800) 344-4255 • 970823-02

FORM # CA-LASER

READ IMPORTANT INFORMATION ON REVERSE SIDE