[redacted]

[redacted]

ich habe nun das Angebot von Mogparts in England erhalten. Siehe untetn.
Habe die Preise in einer Tabelle zusammengestellt:

Pos.:	Artikelnummer:	Neue Nummer	Menge:	Artikelbezeichnung englisch:	MogParts Stk:	Mogparts Stk in €:	Mogparts alle in €:	Oldtimer Zentrum Stk:	Oldtimer Zentrum alle:
1	?		2	refer to MBC section					
1a	MBC4570	BDM066R	1	door ali tread plate rh	£25,80	29,15 €	29,15 €	77,70 €	77,70 €
1b	MBC4571	BDM066L	1	door ali tread plate lh	£25,80	29,15 €	29,15 €	77,70 €	77,70 €
2	MTR0510		1	oil seal mainshaft rear		0,00 €	0,00 €	17,67 €	17,67 €
3	MTR0550		1	oil seal front		0,00 €	0,00 €	9,57 €	9,57 €
4	MTR0560		1	oil seal rear		0,00 €	0,00 €		0,00 €
5	MRA0420		1	pinion oil seal 7HA	£31,00	35,03 €	35,03 €	39,12 €	39,12 €
6	MRA1130	TSM241	1	rear cover gasket 7HA	£6,50	7,35 €	7,35 €	6,40 €	6,40 €
7	MGB0420	NBO047HB	8	propshaft bolt 7HA front & rear	£0,60	0,68 €	5,42 €	2,84 €	22,72 €
8	MGN0125	TSM102N	8	nut	£0,58	0,66 €	5,24 €	2,12 €	16,96 €
9	MXC0102	MXC0132	2	gasket manifold to front pipe	£10,50	11,87 €	23,73 €	15,89 €	31,78 €
10	MXC0132	EXF331	2	gasket manifold to front pipe	£4,00	4,52 €	9,04 €	3,60 €	7,20 €
11	MEC1500	ENR410	2	engine mounting rubber	£79,80	90,17 €	180,35 €	128,70 €	257,40 €
12	MGN0250		4	engine mounting nut		0,00 €	0,00 €	2,93 €	11,72 €
13	?	TSC331	1	clutch	£351,80	397,53 €	397,53 €	344,60 €	344,60 €
14	MEC0130	COE211	1	water pump	£251,60	284,31 €	284,31 €	193,40 €	193,40 €
15	MEC0132		1	water pump gasket		0,00 €	0,00 €		0,00 €
							1.006,31 €		1.113,94 €

[redacted]

[redacted]

MBC4570 our part number BDM066R £17.60
MBC4571 our part n umber BDM066L £17.60
Oil seal main shaft rear our part number is TSG712A for the LT77 gearbox
Oil seal main shaft rear our part number is TSG712 for the R380 gearbox
Oil seal front our part number TSG711 £25.30
Pinion seal our part number TSM212 £31.00
MR1130 our part number TSM241 £6.50
MGB0420 our part number NBO047HB £0.60 each
MGN0125 our part number TSM102N £0.58 each
MXC0102 use MXC0132
MXC0132 our part number EXF331 £10.50 each
MEC1500 our part number ENR410 £79.80 each
MGN0250 nut comes with mount
Clutch kit TSC331 £351.80
MEC0130 our part number COE211 comes with gasket £251.60

Prices do not include carriage

[redacted]

New Morgan 3 & 4 Wheelers For Sale & Hire

[redacted]

0

[redacted]

Perfect! I´m happy!

[redacted]


Thanks for this, part 23 is the threshold strip (ali tread plate) which you have ordered under numbers MBC4570 and MBC4571.
If you're happy that we're talking about the same parts we'll get prices out to you.

[redacted]

you mean this?:

1	?	2	refer to MBC section	Jul 04	216	23	208 es wird auf MBC section verwiesen sollte der passende Artikel zu Pos 1 rechts sein
1a	MBC4570	1	door ali tread plate rh	Jul 04			8
1b	MBC4571	1	door ali tread plate lh	Jul 04			8 sollte der passende Artikel zu Pos 1 links sein

With this items I mean the Number 23 in this Picture:



Greetings
Sascha

[redacted]

Many thanks for this enquiry.
We need a bit of clarification on item 1. On the diagram it's the bumper – is this what you want? If not, could you please describe the part needed and maybe send a picture?

Kind Regards,
Jenny Roberts

Melvyn Rutter Ltd, The Morgan Garage, Little Hallingbury, CM22 7RA

Email: jenny@melvyn-rutter.net
Tel: +44 (0) 1279 725725
www.melvyn-rutter.co.uk
www.mogparts.net

New Morgan 3 & 4 Wheelers For Sale & Hire

[redacted]

Subject: Fwd: Request for quotation spare parts Morgan

Begin forwarded message:

[redacted]

Dear Ladies and Gentlemen,

For a Morgan Plus 8 with 3.5 EFI 143KW from May 22nd, 1987 with VIN R9821 the parts listed in the Excel list would be required.
I got the part numbers from the Morgan Parts Book from 2004.
Please pay attention to item 1 on the article. It is shown in the picture, but there is no part number for it. There is a link to another section. Hope to have identified the correct parts there.
A clutch kit (item 13) is also required. Unfortunately you cannot see the correct part number here in the Parts Book.
Hope you can determine the correct parts from the vehicle data.
Unfortunately the part numbers in the PartsBook are different from those on the homepage. Therefore I would like to ask you to make me an offer for these parts.
Please send me an offer for these parts.
Many Thanks!
With best regards from germany
[redacted]

[redacted]











C
























[redacted]










[redacted]

vom 04.12.20 18:24




vom 04.12.20 18^{03} h



vom 04.12.2020 18:03 h




vom 04.12.2020 18034





vom 04.12.2020 18.03 h









[redacted]

18.03.4



vom 04.12.2020 18.03 h




vom 04.12.2020 18034





[redacted]

Vom 04.12.2020 19 12 4



[redacted]

[redacted] vom 04.12.2020 19:49 h



[redacted] vom 04.12.2020 19 49 4



[redacted]

Vom 05.12.2020 07^{45} h

[redacted] ja, das ist schon eine heftige Arbeit! Heute geht es weiter. Ziel für heute ist es den Motor samt Getriebe auszubauen. Vielleicht dann noch die Kupplung tauschen. Mal sehen, wie spät es wird. Besonders schwierig waren eine Schrauben von unten, die beim Fahren mal irgendwo hängengeblieben sind. Ich würde die alle neu machen und vor allen die, die ständig Wind und Wetter ausgesetzt sind aus Edelstahl nehmen. Außerdem so einige Schläuche. Beispielsweise Kraftstoffleitungen, welche schon sehr hart sind. Da kommt man jetzt wunderbar dran. Auch die Elektrik, wie die Zusatzhupe und die Zusatzscheinwerfer. die sind freiflugmäßig bis vorne verlegt. Das geht besser. Ach, und das Getriebe ist ja sehr versifft. Wenn es gleich draußen ist, schaue ich mal, was es ist. Ich denke, es wird der hintere Simmering sein. Den würde ich auch gleich neumachen wollen. Frage: Welches Zeitfenster geben Sie mir? Ich rechne noch mit etwa 5 Samstagen, wobei ich auch gerne mal den ein oder anderen ausfallen lassen möchte. Sprich so Mitten bis Ende Februar. Ist das in Ordnung, oder wollen Sie vorher eine Fahrt machen? Die Indian dann im Anschluss. Sie steht sicher und abgedeckt in einer Ecke! Weitere Bilder schicke ich dann heute Abend. Viele Grüße

[redacted]

[redacted]

vom 05.12.2020 14^{27} h




[redacted]

vom 05.12.2020 14:27 h





[redacted]

[redacted]






LC03LR002A


FTE
EURO




[redacted]




[redacted]




[redacted]



[redacted]






[redacted]




[redacted]



[redacted]





[redacted]



[redacted]

[redacted]









[redacted]

[redacted]



[redacted]




[redacted]





[redacted]


W 930/20

[redacted]



[redacted]




[redacted]







[redacted]







[redacted]



[redacted]




[redacted]





[redacted]



[redacted]

