1965 Green Austin Healey

From: Anthony Cordasco
54 yard Road
Stockton, N.J.
USA

To: Paul Van De Velde
Zwinlaan 7
PO Box 2
8300 Knokke (Belgium)

Contents of Box:
(Loose parts of car boxed so they don't get lost)

2 rubber floor mats
1 Tonneau cover
1 soft Top cover
1 box with brake shoes and brake cylinder
2 small springs
1 package of old carburetor parts
1 Antique license plate
1 wire wheel hammer
1 Door seal strip (4 yards) #249-607
1 Top Rail seal # 682-360
2 Door waist seals # 9-9306
9-9307

CUSTOMS

Paul

6 1/2 l olie	33
stuur + pon olie	16
zode mist fare + draad + klemmen	22.
2 lampen + battery	15
Rader + ploat	
Boite olie	15
Rem olie + benodigheden	10
werk + lanook 26 X 15 +	400
	511 €
eek/semaine Rutex wax.	18
	529

notities Soub

23/08/2017 (4H)

notes

2 l olie	12,00
2 l olie	12,00
~~[illegible] + factor~~	~~15~~
werk.	330
~~[illegible]~~	~~[illegible]~~
dashboard uitnemen, in/out	354 €
voorruiten in/out	

HealeyParts.nl

Flex Automotive
Wim Janzen
Achterweg 94
4171 BD Herwijnen
Tel. 06-24198007
w.janzen@flexautomotive.nl
www.flexautomotive.nl

[redacted]

Herwijnen, 6 maart 2017

Factuurnummer: **2017**
Debiteurnummer: **1675**

Specificatie:	**Kenteken:**
	Km./ Ml. :

Code	Aantal	Omschrijving		Prijs
DS4240	1	RADIOPLAAT- BJ8	€	14,69
DS4230	1	RADIOPLAAT CHROOMRAND - BJ8	€	8,38
EM4030	1	3000 EMBLEEM, BT7-BJ8	€	16,42
EM4100	2	EMBLEEM MONTAGE CLIPS (KOFFERKLEP), BN1-BJ8	€	0,90

op 6 maart 2017 verzonden naar:
DECA n.v.
Antoon Catriestraat 21
9031 Drongen België

Sub-totaal		€	40,38
Bij: Omzetbelasting	21%	€	8,48
Verzendkosten		€	6,75
Totaal		€	55,62

Wij verzoeken u het **te betalen bedrag binnen 7 dagen** na de factuurdatum over te willen maken op onderstaande bankrekening onder vermelding van het factuur- en debiteurnummer.

Bankgegevens; IBAN: NL43 INGB 0683 3968 38 BIC: INGBNL2A

BTW-nr: NL 8084.07.569.B.01

HealeyParts.nl



[redacted]

dhr. JK

Herwijnen, 17 februari 2017

Factuurnummer: **2017022**
Debiteurnummer: **1675**

Specificatie:	**Kenteken:**
	Km./ Ml. :

Code	Aantal	Omschrijving		Prijs
BU4191	1	KENTEKENPLAATHOUDER VOOR BN4-BJ8	€	21,00
BP4070	1	DEURPANEEL, SET ZWART - BJ8	€	150,00
BP4280	1,5	ZWART VINYL 1,40 M.BREED, PER METER	€	34,88
AK4100	1	ACHTERKLEP AFDICHTRUBBER BN1-BN2	€	20,63
WI4230	1	HOUTEN SLEUTEL - 2 OORIGE SPINNERS - AR	€	19,50
SP4045	2	RUBBER ONDER VOET, SPIEGEL SP4040/ 41	€	3,48
SI4096	1	SCHROEF EN RING SET GEPOLIJST - BN1-BJ8	€	19,39
SK4405	1	CLAXONKNOP, VERSTELBAAR STUUR BN4-BJ8	€	33,00
BD4410	1	ACCU - 12 VOLT ONDERPLAAT BN4,BT7,BJ7,BJ8	€	27,64
BD4420	1	ACCU AFDEKKING 12 VOLT ACCU BN4,BT7,BJ7,BJ8	€	12,19
TB4173	1	BRITISH RACING GREEN LAK - SPUITBUS	€	19,50
DS4250	1	CHROOMRAND POOK DOORVOER - BJ8	€	29,95
DS4210	1	SPEAKERRAND - CHROOM - BJ8	€	26,32
DS4220	1	SPEAKER ROOSTER - BJ8	€	16,09

Sub-totaal		€	433,55
Bij: Omzetbelasting	21%	€	91,05
Verzendkosten		€	36,00
Totaal		€	560,60

Wij verzoeken u het **te betalen bedrag binnen 7 dagen** na de factuurdatum over te willen maken op onderstaande bankrekening onder vermelding van het factuur- en debiteurnummer. bd 17/02

Bankgegevens; IBAN: NL43 INGB 0683 3968 38 BIC: INGBNL2A

BTW-nr: NL 8084.07.569.B.01 www.HealeyParts.nl

PHILIPS CLASSICS BVBA
Industriezone "Op 't Reeck" - Boostveld 1320/4
3770 Riemst - Belgie
Tel. +32(0)12263248
Fax +32(0)12262160
BTW nr. BE 0824.304.812
Email info@philipsclassics.be

[redacted]

Klantnummer	Leveringsbon	Datum	Vervaldag	BTW-nummer klant
VANDE2	**110002081**	22-02-2017		

Artikel-numnmer	Omschrijving	Aan-tal	Een-heid	Eenh.-prijs	Bedrag	BTW %
° MS-MCC299	ASTON CAP COMPONENT	1	St	41,32	41,32	21
° MS-GSS154	FUEL CAP LOCK SS VENT	1	St	16,53	16,53	21
°	Map pockets - small	2		9,92	19,84	21
° MS-VERZ	POST&PACKING	1	St	5,79	5,79	21

Basis	83,48	
BTW %	21	
BTW bedrag	17,53	

ING IBAN BE02 3631 5818 7640 BIC BBRUBEBB

TOTAAL NETTO	€	83,48
TOTAAL BTW	€	17,53
TE BETALEN	€	**101,01**

HIGHLAND AUTOMOTIVE
Route 9W P.O. Box 412
HIGHLAND, NEW YORK 12528
(914) 691-2265

№ 1828

203-743-7651-W

NAME [redacted]
ADDRESS
CITY
PHONE 203-795-0660-H
CUSTOMER'S ORDER NO.
DATE 8-16-88
PROMISED
A.M.
P.M.
ORDER WRITTEN BY Gabe
LICENSE NUMBER
TERMS
ODOMETER

YEAR, MAKE AND MODEL 1967 Austin Healey
SERIAL NUMBER
MOTOR NUMBER

QTY.	PART NO. AND DESCRIPTION	PRICE	
1	U-joint		18.42
1	Clutch Master kit		14.12
1	Drive Shaft flange		20.00
1	~~Clutch master kit~~		~~19.97~~
1	Brake master kit		19.97
1	heater control valve		49.95
1	New Hot Speedo drive		19.95
6	Window Guides	1.59	9.54
4ft	Hosehose	.90	3.60
1	gal anti freeze		10.85
1 pt	brake fluid		3.50
	Speedo drive core charge		10.00

DESCRIPTION OF WORK — AMOUNT

LUBRICATION ☐ CHANGE OIL ☐ OIL FILTER ☐ TUNE UP ☐
TRANSMISSION ☐ DIFFERENTIAL ☐ WASH ☐ POLISH ☐

Install gross jets & adjust carbs & tune
Rebuild clutch & brake master cyl
Replace water control valve, water hoses
Replace speedometer gear drive
Install rear sent belt
Check front end & steering
Install window guides, fish finder
Road test

10 hrs @ 32.00

ALS. OF GAS @
TS. OF OIL @
F GREASE @
Shipping Charges

TOTAL LABOR 320.00
TOTAL PARTS 219.90
ACCESSORIES 10.60
GAS, OIL AND GREASE
OUTSIDE REPAIRS
550.50
TAX 38.53
Thank You
TOTAL 589.03

orize the above repair work to be done along with the aterials. You and your employees may operate above rposes of testing, inspection, or delivery at my risk. An anics lien is acknowledged on above vehicle to secure repairs thereto. It is also understood that you will not nsible for loss or damage to cars or articles left in cars , theft or any other cause beyond your control.

SIGNATURE

TOTAL ACCESSORIES

Enclosed are receipts for all mechanical work that was done; as well as a notarized Bill of Sale

Jack

FORM A 0004 (VEBS) Inc., Lenox Mass. 01471. To Order PHONE TOLL FREE 1-800-225-6380

HIGHLAND AUTOMOTIVE
Route 9W P.O. Box 412
HIGHLAND, NEW YORK 12528
(914) 691-2265

№ 1396

QTY.	PART NO. AND DESCRIPTION	PRICE	
1	CARB Cleaner	3.67	3.67
1	Throttle shaft Bushing		4.85
1	Fan belt		10.20
1	firewall throttle grommet		5.15
1	cooper oil filter		9.95
8 qts	20 w-50 Pennzoil	1.75	14.00
1	used harmonic balancer		45.00
1	balancer Key		1.00
2	Exhaust hangers	4.15	8.30
2	" flange gaskets	5.35	10.70
1	Destributor Cap		16.21
1	Ignition wire set		13.36
1	slave cyl. kit		5.08
1	Clutch Hose		23.65
1	Brake Shoe set		14.36
1	wheel cyl. Kit		7.60
1	Caliper repair kit		34.02
1	brake pad set		13.95
1	used front shocks		35.00
1	Qt Brake fluid		7.00
1	trans. bushing & spring		14.95
	(MAY BE CONTINUED ON OTHER SIDE) TOTAL PARTS		298.00

[redacted]
CITY

CUSTOMER'S ORDER NO.	DATE
203-	12-8-86
PHONE	PROMISED
743-7651	A.M. / P.M.
ORDER WRITTEN BY	
Gabe	

YEAR, MAKE AND MODEL	SERIAL NUMBER	LICENSE NUMBER	TERMS
1965 Austin Healey 3000	MOTOR NUMBER	ODOMETER	

DESCRIPTION OF WORK	AMOUNT
LUBRICATION ☐ CHANGE OIL ☐ OIL FILTER ☐ [illegible] ☐	
TRANSMISSION ☐ DIFFERENTIAL ☐ WASH ☐ [illegible] ☐	
Replace front brakes, rear shoes, rebuild calipers & wheel cyls. turn rotors, clean, pack & adjust wheel bearings. Replace water pump, harmonic balancer & key. Tune engine. Clean oil pan, change oil, filter & lube. repair exhaust system, emergency brake, horns & gas gauge. Replace shocks bushing & spring. Repair R/F shock tower & replace shock. Rebuild clutch slave & replace hose.	24 hrs @ $18.00

ACCESSORIES			
2	Reface front Rotors	10.00	20.00
	TOTAL ACCESSORIES		

Paid 20 12-22-86

LITERS/GALS. OF GAS @	
LITERS/QTS. OF OIL @	
kg/LBS. OF GREASE @	
TOTAL LABOR	672.00
TOTAL PARTS	298.00
ACCESSORIES	
GAS, OIL AND GREASE	
OUTSIDE REPAIRS	20.00
	990.00
TAX	69.30
TOTAL	1059.30

I hereby authorize the above repair work to be done along with the necessary materials. You and your employees may operate above vehicle for purposes of testing, inspection, or delivery at my risk. An express mechanics lien is acknowledged on above vehicle to secure the amount of repairs thereto. It is also understood that you will not be held responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond your control.

Reface Rotors

Thanks

SIGNATURE

No. 2419

FORM 655-3 NEBS Inc., Groton Mass. 01471. To Order PHONE TOLL FREE 1 + 800-225-6380 (Mass. residents 1 + 800-252-9226)



MOSS MOTORS, LTD.
440 RUTHERFORD STREET
GOLETA, CA 93117
800-235-6954

729356

SHIP TO

[redacted]

SOLD TO

908-627-7450

RETURNS - Please see the back of this invoice.
CORE CHARGES - Any core charge shown on this invoice will be refunded upon receipt of a complete, rebuildable core and a copy of this invoice.

CUSTOMER #	P.O. #	BACKORDERS	SOLD BY	SHIP VIA	DATE	INVOICE
302868	SOMERFEST		88 JOE CAPELLA	PRIORITYMAIL	08/18/97	913865

ORD	SHIP	B/O	ORDERED #	STOCKING #	DESCRIPTION	PRICE	EXTENSIO
SHIPPED FROM WH 2, DOVER, NEW JERSEY							
1	1	0	241-735	241-735	A-H FENDER COVER	19.95	19.95
4	4	0	249-607	249-607	DOOR SEAL BLK /YD.	12.80	51.20
1	1	0	021-778	021-778	RUBBER END CAP R/H	2.50	2.50
1	1	0	021-779	021-779	RUBBER END CAP L/H	2.50	2.50
1	1	0	682-360	682-360	TOP RAIL SEAL	16.95	16.95
1	1	0	633-785	633-785	SPEAKER SCREEN BEZEL BJ8	27.45	27.45
1	1	0	544-730	544-730	BRACKET, REFLECTOR, LH	14.25	14.25
1	1	0	544-720	544-720	BRACKET, REFLECTOR, RH	14.25	14.25
					SUBTOTAL		149.05
					TAX		8.94
					TOTAL		157.99
			4442-9601-3941-7689	03/98 AUTH #:_____	VISA		157.99
							0.00

DURING STRIKE-GROUND ORDERS SENT PRI-MAIL AT GROUND RATES!!!

*IMPORTANT ABBREVIATIONS

NYA- Not Currently Available - It may be available in the future.
NWA- Notify When Available - Not currently available, but we will to notify you when it is.
NLS-No Longer Supplied - Not available, and we do not plan to manufacture.



MOSS MOTORS, LTD.
440 RUTHERFORD STREET
GOLETA, CA 93117
800-235-6954

202
361
9358

603826

SHIP TO

[redacted]

SOLD TO

908-627-7450

RETURNS - Please see the back of this invoice.
CORE CHARGES - Any core charge shown on this invoice will be refunded upon receipt of a complete, rebuildable core and a copy of this invoice.

CUSTOMER #	P.O. #	BACKORDERS	SOLD BY	SHIP VIA	DATE	INVOICE
302868			14 JACK, EXT 3193	UPS GRD	02/19/97	819283

ORD	SHIP	B/O	ORDERED #	STOCKING #	DESCRIPTION		PRICE	EXTENSIO
SHIPPED FROM WH 2, DOVER, NEW JERSEY								
6	6	0	529-120	529-120	GASKET, CARB 2 INCH		0.95	5.70
8	8	0	310-140	310-140	NUT		0.25	2.00
8	8	0	365-730	365-730	LOCKWASHER 5/16 IN		0.25	2.00
8	8	0	365-720	365-720	WASHER		0.15	1.20
2	0	2	696-030	696-030	AIR FILTER GSKT 2 IN	*	0.00	0.00
			UNSHIPPED ITEM ABOVE IS ON BACKORDER. IT WILL BE SHIPPED TO YOU ASAP.					
			PART AT NO CHARGE DUE TO SALES SENT OUT WRONG GASKET INV 802973					
					SUBTOTAL			10.90
					TAX			0.65
					SHIPPING & HANDLING			4.70
					TOTAL			16.25
			4417-1125-1111-0415 10/99 AUTH #:_____		VISA			16.25
								0.00

SEE MOSS ON THE WORLD WIDE WEB: HTTP//WWW.MOSSMOTORS.COM

*IMPORTANT ABBREVIATIONS

NYA- Not Currently Available - It may be available in the future.
NWA- Notify When Available - Not currently available, but we will to notify you when it is.
NLS-No Longer Supplied - Not available, and we do not plan to manufacture.



MOSS MOTORS, LTD.
440 RUTHERFORD STREET
GOLETA, CA 93117
800-235-6954

583300

SHIP TO

[redacted]

SOLD TO

908-627-7450

RETURNS - Please see the back of this invoice.
CORE CHARGES - Any core charge shown on this invoice will be refunded upon receipt of a complete, rebuildable core and a copy of this invoice.

CUSTOMER #	P.O. #	BACKORDERS	SOLD BY	SHIP VIA	DATE	INVOICE
302868			08 AARON, EXT 3206	UPS GRD	01/14/97	802973

ORD	SHIP	B/O	ORDERED #	STOCKING #	DESCRIPTION		PRICE	EXTENSIO
SHIPPED FROM WH 2, DOVER, NEW JERSEY								
2	2	0	162-700	162-700	DRIVING LAMP CLEAR LENS RED TAG SALE FEB 1997		69.95	139.90
3	3	0	378-360	378-360	GASKET, FLOAT LID		0.66	1.98
2	2	0	696-010	696-010	GASKET, CARB-INTAKE		0.95	1.90
2	2	0	696-020	696-020	AIR CLEANER GSKT- 1 3/4		0.75	1.50
1	1	0	PL	PL	PRICE LIST		0.00	0.00
1	1	0	231-670	231-670	CAR DUSTER RED TAG SALE FEB 1997		8.95	8.95
					SUBTOTAL			154.23
					TAX			9.25
					SHIPPING & HANDLING			11.90
					TOTAL			175.38
			4417-1125-1111-0415 10/99 AUTH #:_____		VISA			175.38
								0.00

THANK YOU FOR YOUR ORDER. WE APPRECIATE YOUR PATRONAGE.....

*IMPORTANT ABBREVIATIONS

NYA- Not Currently Available - It may be available in the future.
NWA- Notify When Available - Not currently available, but we will to notify you when it is.
NLS-No Longer Supplied - Not available, and we do not plan to manufacture.

MOSS MOTORS, LTD.
440 RUTHERFORD STREET
GOLETA, CA 93117
800-235-6954

552774

SHIP TO

[redacted]

SOLD TO

908-627-7450

RETURNS - Please see the back of this invoice.
CORE CHARGES - Any core charge shown on this invoice will be refunded upon receipt of a complete, rebuildable core and a copy of this invoice.

Janet
Klaus

CUSTOMER #	P.O. #	BACKORDERS	SOLD BY	SHIP VIA	DATE	INVOICE
302868			16 JENNIFER, EXT 3184	UPS GRD	11/15/96	779727

ORD	SHIP	B/O	ORDERED #	STOCKING #	DESCRIPTION		PRICE	EXTENSI
SHIPPED FROM WH 2, DOVER, NEW JERSEY								
1	1	0	CTOP	CTOP	COMMENT TO FOLLOW		0.00	0.00
			THIS IS A PRESENT SO CONTACT SHOULD BE MADE TO JULIE GEROW ONLY					
1	1	0	236-125	236-125	CAR COVER TECHNALON		154.95	154.95
					SUBTOTAL			154.95
					TAX			9.30
					SHIPPING & HANDLING			11.90
					TOTAL			176.15
			4820-0351-7834-0283 06/98 AUTH #:_____		V			176.15
								0.00

THANK YOU FOR SUPPORTING MOSS - WE APPRECIATE YOUR BUSINESS

*IMPORTANT ABBREVIATIONS

NYA- Not Currently Available - It may be available in the future.
NWA- Notify When Available - Not currently available, but we will to notify you when it is.
NLS-No Longer Supplied - Not available, and we do not plan to manufacture.

RO#001

William Thomas Roadsters, LLC

Name: [redacted]		**Date: November 21, 2013**	
Addres [redacted]		**Tel: 908 788 7866**	**Cell:**
Vehicle: Austin Healey	**Model: 3000 BJ8**	**Year: 1965**	
VIN: HBJ8L31322	**Miles: 77,872**	**LABOR RATE $99.00/hr**	

Item #	Repair operation	Labor	Parts	Misc.
1	Engine will not crank. Inspect and diagnose starting system fault. Starter motor worn out and completely inoperative. Remove old starter and install new high-torque modern assembly. Bypass original solenoid and wire new starter circuit as required.	2.0	$274.95	Shipping$ 15.95
2	Replace broken heater control panel. Remove arm rest and center console assembly. Remove all switches and plinth assembly. Clean corrosion from chrome surface of plinth. Disassemble heater control head and remove plastic panel. Lube air control knob/cables to ease friction. Install new panel and reassemble control head. Reassemble dash switches and install console/arm rest assemblies. Test all circuits.	4.0	Heater panel $7.95	
3	Check for hesitation/bucking at higher speeds and throttle loading. Inspect breaker points and rotor. Points corroded causing hard intermittent bucking due to arching. Replace points and set engine specs. Road test. Bucking eliminated. Check mixtures. Running slightly lean causing higher speed surging. Inspect fuel. Very stale. Drive to gas station and fill tank with fresh premium fuel. Drive until fresh fuel fully ingested into carburetors. Surging eliminated via fresh fuel. Carburetor mixtures OK, fuel was cause of surging.	1.5		$20.00 Fuel
4	Perform final road test of vehicle. Runs perfectly.	n/a		
5	**NOTE**: Per our conversation regarding fuel contamination and degradation as well as corrosion found on breaker points (both of which caused the poor running condition), this scenario will continue to recur as long as vehicle is stored in its existing damp, uncontrolled environment. Paint degradation and subsurface oxidation will worsen as well. I would highly recommend having vehicle professionally detailed throughout including major polish and sealing of exterior finish. Rodent infestation is also a major problem in trunk and interior of vehicle. Controlled storage of vehicle is urged in order to maintain mechanical and cosmetic integrity.			
	Total Labor:	7.5 hours $742.50		
	Total Parts:		$282.90	
	Total Misc:			$35.95
	Sub Total:	$1061.35		
	Tax@ 7%:	$74.29		
	Grand Total:	$1135.64		

RO#001

William Thomas Roadsters, LLC

Name: [redacted]		**Date: March 13, 2012**	
Addre: [redacted]		**Tel: 908 788 7866**	**Cell:**
Vehicle: Austin Healey	**Model: 3000 BJ8**	**Year: 1965**	
VIN: HBJ8L31322	**Miles: 77,548**	**LABOR RATE $88.00/hr**	

Item #	Repair operation	Labor	Parts	Misc.
1	Check engine miss at cold start-up. Engine in need of full tune. Plugs fouled, ignition wires arching, point corroded and ignition coil leaking oil. Perform full tune. Replace distributor cap, spark plugs, breaker points, distributor rotor (with premium unit), distributor battery lead/block assembly, ignition wires and ignition coil. Coil was leaking oil badly and would have failed due to overheating. Set ignition timing. Adjust carburetor mixtures and synchronize. Set fast-idle speed and curb idle. Road test several times to set mixtures. Set oil level in carburetor dashpots. Inspect air filter condition. Repair vacuum leak.	4.0	6 plugs $21.00 Points $7.95 Distrib. Cap $19.90 Wire set $28.99 Premium rotor $14.00 Wire lead $9.90	
2	Replace fuel pump with OEM-style Lucas transistorized unit. Replace rubber fuel lines at tank and pump. Install fuel filter between fuel tank and new pump. Replace all clamps and wire connectors. Replace fuel filter located before carburetors. Install new rubber fuel hoses and clamps in this location as well.	1.5	Pump $210.95 2 fuel filters $16.00 8 line clamps $8.00 30" fuel line $5.00	Shipping $12.95
3	Check hot-running condition. Vehicle does heat up if left to idle too long. This is a typical condition. In order to reduce or eliminate this condition, I would recommend a new radiator and auxiliary electric cooling fan installation. Vehicle does not boil over and runs at completely normal temp while being driven normally. Only when left to idle too long will it heat up.	N/C		
4	Check shocks for leaks or wear. Shocks not leaking and feel like they have plenty of compression and rebound damping control.	N/C		
5	Replace 5 tires. Install 5 new Vredestein 165/70x15 tires.		5 tires at $159.99 $799.95	Sublet mounting and balancing $100.00
6	Check emergency brake - sticks. Lubricate and work linkage loose. Adjust cable length.	1.0		
7	Wire fog lights, fabricate switch mount, install switch. Route wires	2.5		8 ft wire,

	and affix neatly through engine bay and core support area.			elec. Conn. Switch, Materials $25.00
8	Check battery polarity. Vehicle is POSITIVE ground.			
9	Change oil and filter	.4	6.5 quarts Agip oil $36.00 1 zinc additive $10.00 1 filter $9.90	
10	Check exhaust leaks. System must be unbolted and re-installed using supplemental clamps. Tighten existing clamps wherever possible.	.3		
11	Change differential oil. Gearbox oil change will require removal of center console and transmission tunnel carpeting to access fill port. Must reschedule.	.3	4 pints oil $28.00	
12	Clean vehicle exterior and interior. Road test and install $15.00 premium fuel.			$15.00 fuel
	Total Labor:	$880.00		
	Total Parts:		$1225.54	
	Total Misc:			$152.95
	Sub Total:	$2258.49		
	Tax@ 7%:	$158.09		
	Grand Total:	$2416.58		

Auto Repair Order

John Davies
312 Park Avenue
Chalfont, Pennsylvania 18914
215 ▪ 822-8965 Phone / Fax

GREEN.

Date: _____

Name: [redacted] Home Phone #: _____

Address [redacted] Work Phone #: _____

City: N/S 54 YARD RD STOCKTON

Year: 66 Make: A/H Model: BJ8 Mileage: _____

Serial Number: _____ License No.: _____

QUAN.	PART NUMBER AND DESCRIPTION	PRICE	AMOUNT
1	THERMOSTAT GASKET.		1.10
6	RN 12Y PLUGS.		14.40
1	CLUTCH PRESSURE PLATE.		140.00
2	BRAKE FLEX HOSES.		57.00
	COD + SHIP.		16.45
4	UPPER BUSHINGS		12.00
4	CALIPER PISTONS.		80.00
	COD + SHIP.		14.95
1	SPIN ON OIL FILTER KIT + SHIP		53.45
1	CALIPER SEAL KIT		19.00
1	PT STAINLESS STEEL PAINT.		11.75
	COD + SHIP.		15.35
1	OIL FILTER.		6.80
1	QRT 10W 40		2.40
	BRAKE FLUID		4.00
	OWNERS PADS		
	(TEMP GAUGE IS 20° TO HIGH)		
			448.65

OPER. NO.	INSTRUCTIONS	AMOUNT
	INSTALL REAR REFLECTORS.	
	CHECK OUT BRAKES. REBUILD CALIPERS.	
	CHECH OUT CLUTCH OPERATION.	
	CHECK THERMOSTAT. 160°	
	INSTALL RUBBER GROMMET ON GAS FILLER TUBE.	
	REPAIR R-REAR AXLE BUMP STOP.	
	SCREW IN HEATER CONTROL KNOB	
	INSTALL LATCH ON R.S. TOP. . INSTALL BRAKE PADS.	
	TIGHTEN IGNITION SWITCH.	
	INSTALL REAR BRAKE FLEX HOSE. INSTALL 2 FRONT HOSES.	
	R+R BRAKE CALIPERS FOR REPAIR. (TAKE APART)	
	INSTALL UPPER BUSHINGS ON KING PINS.	

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH THE NECESSARY MATERIALS. I HEREBY GRANT YOU AND YOUR EMPLOYEES PERMISSION TO OPERATE THE VEHICLE ABOVE DESCRIBED ON STREETS, HIGHWAYS, OR ELSEWHERE FOR THE PURPOSES OF TESTING, INSPECTION AND DELIVERY. AN EXPRESS MECHANIC'S LIEN IS HERBY ACKNOWLEDGED ON THE ABOVE DESCRIBED VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERE TO.

IT IS UNDERSTOOD THAT YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS, OR DAMAGE TO THE ABOVE DESCRIBED VEHICLE, OR ARTICLES LEFT THEREIN, IN CASE OF FIRE, THEFT, ACCIDENT OR OTHER CAUSE BEYOND YOUR CONTROL.

SIGNED DATE / /

TOTAL LABOR *	805.00
TOTAL PARTS *	448.65
GAS, OIL, GREASE *	
OUTSIDE WORK	
OLD OIL & TIRES	
SUB-TOTAL	1253.65
TAX	75.20
TOTAL $	1328.85

WHITE COPY - OFFICE YELLOW COPY - CUSTOMER

GARAGE REPAIR ORDER

JD AUTO Repair
John Davies
215 • 822-8965
312 Park Ave, Chalfont, PA 18914

NAME [redacted]

ADDRESS [redacted]

HOME PHONE BUSINESS PHONE

DATE 04-09-01.

LICENSE NO. MILEAGE

YEAR/MAKE 65. A/H. BJ8. CONV. MODEL

SERIAL NO.

MOTOR NO.

PROMISED DATE & TIME

CALL WHEN READY? ☐ YES ☐ NO WRITTEN BY

QTY.	PART NUMBER	DESCRIPTION OF PART	AMOUNT
		Owners thermostat	—
1		Clutch master-cylinder.	88.00
		COD ship.	12.25
1		Ignition switch	25.00
		Clutch fluid.	2.00
		Owner heater control cable.	—
2		Cable clips.	5.00
		TOTAL PARTS	132.25

DESCRIPTION OF SERVICES

Install ignition switch

Install clutch master cylinder.
Bleed the clutch.
Install heater cable.
Install thermostat

Check for fuel leak. none found.

GAS/OIL/GREASE	AMOUNT
GAS–_____ GALS. @_____	
OIL –_____ QTS. @_____	
GREASE–_____ LBS. @_____	
TOTAL GAS/OIL/GREASE	

TOTAL LABOR	130.00
TOTAL PARTS	132.25
TOTAL ACCESSORIES	
TOTAL SUBLET	
TOTAL GAS/OIL/GREASE	
SUBTOTAL	262.25
TAX	15.75
TOTAL ALL PARTS & SERVICES	278.00

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL.

AUTHORIZED BY ×

PD 5/2/01

GARAGE REPAIR ORDER

NAM[redacted]

ADDR[redacted]

HOME PHONE [redacted].519.3258.

DATE 4-27-98

LICENSE NO. [redacted] MILEAGE 3000

YEAR/MAKE 67 H/H MODEL BJ8

SERIAL NO.

MOTOR NO.

PROMISED DATE & TIME

CALL WHEN READY? ☐ YES ☐ NO

WRITTEN BY

JD AUTO Repair
John Davies
215 • 822-8965
312 Park Ave, Chalfont, PA 18914

QTY.	PART NUMBER	DESCRIPTION OF PART	AMOUNT
1	Clutch	kit.	230.80
1	Pilot	bearing.	5.35
1	Front	trans dr seal.	4.25
3	Trans	rear mounts.	17.20
1	Clutch	slave cylinder kit.	7.60
1	Brake	fluid.	3.00
3	Rubber	bushings trans strut	3.60
1	U/J.		22.64
		TOTAL PARTS	294.44

DESCRIPTION OF SERVICES

Road test.
Install new clutch.
Check over the front suspension.
Install brake fluid reservoir
Bleed all brakes and the clutch system
Install U/J on front of drive shaft
adjust steering idler play.
Free off RR wheel cylinder (Hagen)

GAS/OIL/GREASE	AMOUNT
GAS-_____ GALS. @_____	
OIL -_____ QTS. @_____	
GREASE-_____ LBS. @_____	
TOTAL GAS/OIL/GREASE	

TOTAL LABOR	440.00
TOTAL PARTS	294.44
TOTAL ACCESSORIES	
TOTAL SUBLET	
TOTAL GAS/OIL/GREASE	
SUBTOTAL	734.44
TAX	44.07
TOTAL ALL PARTS & SERVICES	778.51

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL.

AUTHORIZED BY X _____

Flex Automotive
Wim Janzen

Achterweg 94
4171 BD Herwijnen
Tel. 06-24198007

w.janzen@flexautomotive.nl
www.flexautomotive.nl

[redacted]

Herwijnen, 26 november 2016

Factuurnummer: **2016543**
Debiteurnummer: **1675**

Specificatie: **Kenteken**

Code	Aantal	Omschrijving		Prijs
ac4112	1	vloermatset	€	66,03
RM4750	1	REMBEKRACHTIGER ORG. LOCKHEED - STANDAARD.	€	294,00
	1	remleiding met nippels	€	11,20
RM4770	1	FLEX.BEKR.SLANG - ALLE BEKR.MODELLEN	€	8,91

Servopomp Renault

Sub-totaal		€	380,14
Bij: Omzetbelasting BTW verlegd: BTW nr. BE 0821.016.908	0%	€	-
Verzendkosten			
Totaal		€	380,14

Wij verzoeken u het **te betalen bedrag binnen 7 dagen** na de factuurdatum over te willen maken op onderstaande bankrekening onder vermelding van het factuur- en debiteurnummer.

Bankgegevens; IBAN: NL43 INGB 0683 3968 38 BIC: INGBNL2A

BTW-nr: NL 8084.07.569.B.01

PHILIPS CLASSICS BVBA
Industriezone "Op 't Reeck" - Boostveld 1320/4
3770 Riemst - Belgie
Tel. +32(0)12263248
Fax +32(0)12262160
BTW nr. BE 0824.304.812
Email info@philipsclassics.be

[redacted]

VERMELDEN BIJ BETALING A.U.B.

Klantnummer	Factuur	Datum	Vervaldag	BTW-nummer klant
VANDE2	**170000713**	22-02-2017	01-03-2017	

Artikel-numnmer	Omschrijving	Aan-tal	Een-heid	Eenh.-prijs	Bedrag	BTW %
MS-MCC299	ASTON CAP COMPONENT	1	St	41,32	41,32	21
MS-GSS154	FUEL CAP LOCK SS VENT	1	St	16,53	16,53	21
	Map pockets - small	2		9,92	19,84	21
MS-VERZ	POST&PACKING	1	St	5,79	5,79	21

Leverdatum: 22-02-2017 BTW-opeisbaar: 22-02-2017

Basis	83,48	
BTW %	21	
BTW bedrag	17,53	

ING IBAN BE02 3631 5818 7640 BIC BBRUBEBB

TOTAAL NETTO	€	83,48
TOTAAL BTW	€	17,53
TE BETALEN	€	**101,01**

Flex Automotive B.V.
Achterweg 94
4171 BD Herwijnen

TEL +31 (0)418 820 200
E-MAIL info@healeyparts.nl
KVK 11046426

IBAN NL43 INGB 0683 3968 38
BIC INGB NL2A
BTW NL 8084.07.569.B01

HealeyParts
REVISIE & ONDERHOUD

[redacted]

Herwijnen, 1 mei 2017

Factuurnummer: 2017239M
Debiteurnummer: 1675

Specificatie:	**Kenteken:**
	Km./ Ml. :

Code	Aantal	Omschrijving		Prijs
	1	STEEKAS - 6 CILINDER HEALEY	€	200,00

+ 100 € plaatsing

Marge regeling van toepassing, gebruikte goederen.

Verzendkosten		€	21,50
Sub-totaal		€	221,50
Bij: Omzetbelas	Marge BTW.	0% €	-
Totaal		€	221,50

betr 3/05/2017

Wij verzoeken u het **te betalen bedrag binnen 7 dagen** na de factuurdatum over te willen maken op onze bankrekening onder vermelding van het factuur- en debiteurnummer.

HEALEYPARTS.NL IS EEN ONDERDEEL VAN FLEX AUTOMOTIVE B.V.
Op al onze diensten en leveringen zijn onze voorwaarden van toepassing, gedeponeerd bij KVK.

HealeyParts.nl

Flex Automotive
Wim Janzen

Achterweg 94
4171 BD Herwijnen
Tel. 06-24198007

w.janzen@flexautomotive.nl
www.flexautomotive.nl

[redacted]

Herwijnen, 17 februari 2017

Factuurnummer: **2017022**
Debiteurnummer: **1675**

Specificatie:	**Kenteken:**
	Km./ Mi. :

Code	Aantal	Omschrijving		Prijs
BU4191	1	KENTEKENPLAATHOUDER VOOR BN4-BJ8	€	21,00
BP4070	1	DEURPANEEL, SET ZWART - BJ8	€	150,00
BP4280	1,5	ZWART VINYL 1,40 M.BREED, PER METER	€	34,88
AK4100	1	ACHTERKLEP AFDICHTRUBBER BN1-BN2	€	20,63
WI4230	1	HOUTEN SLEUTEL - 2 OORIGE SPINNERS - AR	€	19,50
SP4045	2	RUBBER ONDER VOET, SPIEGEL SP4040/ 41	€	3,48
SI4096	1	SCHROEF EN RING SET GEPOLIJST - BN1-BJ8	€	19,39
SK4405	1	CLAXONKNOP, VERSTELBAAR STUUR BN4-BJ8	€	33,00
BD4410	1	ACCU - 12 VOLT ONDERPLAAT BN4,BT7,BJ7,BJ8	€	27,64
BD4420	1	ACCU AFDEKKING 12 VOLT ACCU BN4,BT7,BJ7,BJ8	€	12,19
TB4173	1	BRITISH RACING GREEN LAK - SPUITBUS	€	19,50
DS4250	1	CHROOMRAND POOK DOORVOER - BJ8	€	29,95
DS4210	1	SPEAKERRAND - CHROOM - BJ8	€	26,32
DS4220	1	SPEAKER ROOSTER - BJ8	€	16,09

Sub-totaal		€	433,55
Bij: Omzetbelasting	21%	€	91,05
Verzendkosten		€	36,00
Totaal		€	560,60

Wij verzoeken u het **te betalen bedrag binnen 7 dagen** na de factuurdatum over te willen maken op onderstaande bankrekening onder vermelding van het factuur- en debiteurnummer.

Bankgegevens; IBAN: NL43 INGB 0683 3968 38 BIC: INGBNL2A

BTW-nr: NL 8084.07.569.B.01 www.HealeyParts.nl

Austin Healey MKIII.

[redacted]

28/6/17

Zoals gevraagd de herstelling v.d. toerenteller 6cyl elektronic

- herstelling elektronica
- nieuwe ijking
- joint rond huis € 85

PS: 1 beugel voor montage was er niet bij.

Graag overschrijven op rek.nr.:
BE 37 0010 5923 3128

Alvast bedankt.

Met vriendelijke groeten.

Andraj

AUTOBEDRIJF

Demco

Wolfputstraat 28 B-9041 Oostakker Tel: 09/xxx,xx,xx Gsm/ 0475/66,28,20

[redacted]

FAKTUURNR 1801612

DATUM 11.11.18

Artikel	Verrichtingen	Aantal	BTW	Prijs	Totaal
	Plaat nr ; O-ACN-716 km; 78924.				
	HD8 rebuildkit	2	21 %	108,64	217,28
	Damper spring.	2	21 %	25,08	50,16
	Needle UH	2	21 %	19,35	38,7
	Throttle spring.	2	21 %	1,14	2,28
	klein materiaal.	1	21 %	15,00	15
	Werk, revisie SU carburatoren.	8	21 %	25,00	200

VERVALDATUM : kontant.

	6 %	12 %	21 %	0 %		TOTAAL
NETTO			523,42			523,42
BTW			109,92			109,92
TOTAAL			633,34			**633,34**

BTW NR: BE0739,246,896 Bankrekening BE28 8903 9426 5120

Verkoopsvoorwaarde op keerzijde

bet. 18/11

Retro Service Ottevaere

Een passie voor het vak...

SPECIALISATIE OLDTIMERS & CLASSICS

aan- en verkoop - herstellingen - onderhoud - restauratie

www.retroservice.be

openingsuren op onze website

[redacted]AUL

BE:

Factuur nr:	18-069	**Datum factuur:**	16/08/18

Opdracht: HEVIG OLIEVERLIES/ ALGEMEEN NAZICHT EN IN ORDE STELLEN/ GROOT ONDERHOUD

Datum in: 9/07/18 **Datum uit:** 16/08/2018

Gegevens voertuig:					
Merk:	AUSTIN HEALEY	**1ste gebr:**	22/04/1965	**mot.:**	2900/6
type:	3000 MK III (BJ8)	**chass.nr:**	HBJ8L31332		
		nr.plaat:	O.ACN.716	**km:**	78.634

UITGEVOERDE WERKEN:

NAZICHT STAAT ALGEMEEN/ OPSPOREN DEFECTEN/ VERVANGEN: RADIATOR- STABILISATIE DELEN VOORAS- WIELREMCILINDERS ACHTERAAN- HOOFDREMCILINDER- HULP KOPPELINGSCILINDER- KOPPELINGSLEIDING- THERMOSTAAT- KOELLEIDINGEN- CARTERVENTILATIE LEIDINGEN- ONDERDRUKLEIDINGEN- MOTOROPHANGING- BENZINELEIDINGEN AAN POMP EN CARBURATOR- UITLAATOPHANGING- V-RIEM- OLIEDRUK LEIDING- RUITENWISSERS- ONTSTEKINGSROTOR/ HERSTELLEN OLIEVERLIES KLEPPENDEKSEL/ DOORSPOELEN KOELCIRCUIT EN VERVERSEN/ HERSTELLEN KOPPELINGEN REMLEIDINGEN/ DOORSPOELEN REMCIRCUIT EN ONTLUCHTEN/ REINIGEN REMBELEG/ AFSTELLEN REMMEN/ SPOELEN EN ONTLUCHTEN KOPPELINGSCIRCUIT/ ONTROESTEN EN SCHILDEREN DIV. HERSTELDE DELEN/ GRONDIG REINIGEN VAN ALLE HERSTELDE DELEN/ OPSPOREN PROBLEEM TOERENTELLER EN HERSTELLEN/ BEVESTIGEN PINKER VERKLIKKERLAMPJE/ HERSTELLEN DIVERSE SLECHTE CONTACTEN BEDRADING/ HERSTELLEN OF VERVANGEN BEVESTIGINGSMAT./ ONDERHOUD MET MOTOROLIE- OLIE VERSNELL.BAK EN O/D- OLIE DIFFERENTIEEL- OLIEFILTER- BENZINEFILTER- LUCHTFILTERS- BOUGIES- SMERING- VOLL. NAZICHT EN CONTROLES- REINIGEN STROOMVERDELERMECHANISME- REINIGEN OLIEZEEF OVERDRIVE- CONTROLE KOELCIRCUIT EN DRUKTEST- AFSTELLEN KLEPSPELING- AFSTELLEN CONTACTPUNTEN EN ONTSTEKINGSTIJDSTIP- BIJREGELEN CARBURATIE- BIJVULLINGEN- ONTVETTEN MOTOR/ CONTROLES ALGEMEEN

ONDERDELEN:	**AANT.**	**EH-PRIJS**	**TOT.EXCL.**	**BTW%**
OLIEFILTER MANN	1	9,95	9,95	21
AH ENG. MOUNTING UPR	2	15,50	31,00	21
AH ENG. MOUNTING UNF	2	38,60	77,20	21
THERMOSTATH 74°C	1	21,85	21,85	21
AH CUP WASHER R.COVER	2	6,00	12,00	21
GASKET THERM.	1	2,50	2,50	21
AH R.COVER GASKET	1	15,00	15,00	21
SLAVE CYL. UPR.	1	164,00	164,00	21
AH ANTI ROLL LINK SET	1	140,50	140,50	21
WHEEL CYL. LOCK PLATE-SPRING SET	2	28,00	56,00	21

Berchemweg 11
9700 oudenaarde
055/60 35 97
info@retroservice.be

Retro Service Ottevaere dankt u voor het vertrouwen!

GELIEVE DE BETALING TE VERRICHTEN BINNEN DE 8 DAGEN

Garantie op oldtimer onderdelen volgens voorwaarden en na akkoord producent.

Onderdelen zijn inclusief order- en portkosten

BTW: 0863.516.467
BELFIUS: BE40 0682 4597 6263
BIC: GKCC BE BB
ING: BE11 3770 3754 0148
BIC: BBRU BE BB

Retro Service Ottevaere

Een passie voor het vak...

SPECIALISATIE OLDTIMERS & CLASSICS

aan- en verkoop - herstellingen - onderhoud - restauratie

www.retroservice.be

openingsuren op onze website



[redacted]

BE:

Factuur nr:	Datum factuur:

Opdracht:

Datum in: **Datum uit:**

Gegevens voertuig:		nr.plaat:	O.ACN.716	km:	78.634
Merk:	AUSTIN HEALEY	1ste gebr:	22/04/1965	mot.:	2900/6
type:	3000 MK III (BJ8)	chass.nr:	HBJ8L31332		

ONDERDELEN:	AANT.	EH-PRIJS	TOT.EXCL.	BTW%
7" WHEEL CYL	2	92,00	184,00	21
MTR BRAKE 64-67	1	251,00	251,00	21
HIGH PRESS. HOSE CLUTCH	1	18,00	18,00	21
RAD.CAP 7LB	1	19,00	19,00	21
FAN BELT 10/1125	1	15,50	15,50	21
AH RAD/HTR HOSE SET	1	235,00	235,00	21
FLEX OIL PRESS.	1	145,20	145,20	21
AIR FLTR 2" RR.	1	98,10	98,10	21
AIR FLTR 2" FR	1	102,60	102,60	21
EXH. MOUNTING RBR	6	15,00	90,00	21
6 CYL ROTOR H.D.	1	21,80	21,80	21
BOUGIE NGK	6	5,50	33,00	21
BUSH ANTI ROLL 5/8	2	24,00	48,00	21
REVIESIE RADIATOR/ VERSTERKT KOELBLOK	1	644,00	644,00	21
SMEERMIDDELEN/ ONTVETTER	1	15,00	15,00	21
KOPER DICHTINGSRING PLAT	3	3,50	10,50	21
SPLITPEN GR.	2	2,50	5,00	21
REMVLOEISTOF	1,5	18,00	22,50	21
OLIE 75/90 SYNTRAX UNI PLUS GL3	2,5	18,00	45,00	21
BOSAL RUBBER	1	5,00	5,00	21
PAKKING FLEX	2	5,00	10,00	21
REMLEIDING GEMAAKT M. NIPPELS	1	45,00	45,00	21
OLIE 20/50 VISCO 2000 SPEC. M	10	14,00	140,00	21
SPANBAND ABA MINI M BOUT	13	3,75	48,75	21
SPANBAND ABA KL	12	2,50	30,00	21
ONDERDRUKLEIDING 3MM BLAUW /M	1	13,00	13,00	21
BRANDSTOFLEIDING 8MM /M	2,5	18,50	46,25	21
BRANDSTOFFILTER BOSCH	1	18,50	18,50	21
GATES 90° 18MM	1	17,00	17,00	21
BENZ/OLIE LEIDING 16MM /M	0,5	85,00	42,50	21

Berchemweg 11
9700 oudenaarde
055/60 35 97

info@retroservice.be

Retro Service Ottevaere dankt u voor het vertrouwen!

GELIEVE DE BETALING TE VERRICHTEN BINNEN DE 8 DAGEN

Garantie op oldtimer onderdelen volgens voorwaarden en na akkoord producent.

Onderdelen zijn inclusief order- en portkosten

BTW: 0863.516.467
BELFIUS: BE40 0682 4597 6263
BIC: GKCC BE BB
ING: BE11 3770 3754 0148
BIC: BBRU BE BB

Retro Service Ottevaere

Een passie voor het vak...

SPECIALISATIE OLDTIMERS & CLASSICS

aan- en verkoop - herstellingen - onderhoud - restauratie

www.retroservice.be

openingsuren op onze website



[redacted]

BE:

Factuur nr:	**Datum factuur:**

Opdracht:

Datum in: **Datum uit:**

Gegevens voertuig:		**nr.plaat:**	O.ACN.716	**km:**	78.634
Merk:	AUSTIN HEALEY	**1ste gebr:**	22/04/1965	**mot.:**	2900/6
type:	3000 MK III (BJ8)	**chass.nr:**	HBJ8L31332		

ONDERDELEN:	**AANT.**	**EH-PRIJS**	**TOT.EXCL.**	**BTW%**
ADD. CARBURATOR REINIGER	1	18,00	18,00	21
RUITENWISSER CHR. 5,2	2	25,00	50,00	21
2K KIT	0,5	44,00	22,00	21
RUITENREINIGER	1	4,50	4,50	21
RADICOOL CA	11	12,00	132,00	21
MILIEUBIJDRAGE	1	5,50	5,50	21
GEBRUIKTE PRODUKTEN / BENODIGDHEDEN/ KL. MATERIALEN			102,00	21
WERKUREN: 24,5 x € 54,00			1323,00	21
OPMERKINGEN: ALGEMENE STAAT MOTOR +/-				
VERMINDERDE DOORGANG KOELKANALEN MOTORBLOK				
HOOG OLIEVERBRUIK				
LICHTE LEKKAGE KOPPAKKING				

Volgend onderhoud op: 80.600 Mls OF VOOR 16/08/2019

Basis BTW	**EUR.**	4606,20		**EUR.**
% BTW		21		
Bedrag BTW	**EUR.**	967,30	bh 22/07	**5573,50**

Berchemweg 11
9700 oudenaarde
055/60 35 97

info@retroservice.be

Retro Service Ottevaere dankt u voor het vertrouwen!

GELIEVE DE BETALING TE VERRICHTEN BINNEN DE 8 DAGEN

Garantie op oldtimer onderdelen volgens voorwaarden en na akkoord producent.

Onderdelen zijn inclusief order- en portkosten

BTW: 0863.516.467
BELFIUS: BE40 0682 4597 6263
BIC: GKCC BE BB
ING: BE11 3770 3754 0148
BIC: BBRU BE BB

garage dhondt

ALBERTLAAN 52
8300 KNOKKE-HEIST 1
TEL. 050 60 86 75 • FAX 050 60 10 83 • WWW.BOSCHCARSERVICEDHONDT.BE

BTW BE 0889.818.711
KBC 738-0213706-37
BIC: KREDBEBB
IBAN: BE 35 7380 2137 0637

auto-elektriciteit
VERKOOP - PLAATSEN - HERSTELLEN
Starters en alternatoren
Benzine - dieselinjectie
Autohifi -batterijen
Alle Bosch producten

BOSCH Service
Car Service

[redacted]

ONDERHOUD EN HERSTELLINGEN VAN ALLE MERKEN • OOK AMERIKAANSE WAGENS

Voor levering, gedane werken en uitgaven volgens onderstaande beschrijving betaalbaar te knokke, contant zonder disconto.

Pour fournitures, travaux exécutés et debours, dont détail ci-dessous payables à Knokke, au comptant sans escompte.

FACTUUR

BTW-nr Klant	klant nr	doc. nr	datum
	1511	1109	03-08-2019

omschrijving	aantal	eenheidsprijs	%	totaal	BTW
Orderdatum: 03-08-2019 / Ordernr.: 4781 / Voertuig: AUSTIN HEALEY / Chassis: HBJ8L31332 / Plaatnr: OACN716 / Km: 79.104 km / Datum Inschr.: 22-04-1965					
01-08-2019					
DEPANNAGE MET 2 PERSONEN	1	60	0	60,00	4
02-08-2019					
CO GEREGELD	1	12	0	12,00	4
REMMENTEST	1	13	0	13,00	4
LICHTEN GEREGELD	1	12	0	12,00	4
ONTSTEKINGS BOBIJN	1	95,55	0	95,55	4
CLEANER + KL MATERIAAL	1	4,95	0	4,95	4
KEURINGSBEWIJS	1	39,84	0	39,84	4
U. WERK O.T.+NAAR KEURING GAAN	4	60	0	240,00	4

By Carfac ©

BTW	4 = 21 %		
basis	477,34	subtotaal	€ 477,34
bedrag	100,24	totaal btw	€ 100,24
		totaal te betalen	**€ 577,58**

Bedankt en tot ziens !
Like ook onze facebook pagina : Garage Dhondt Bernard !

te vermelden bij betaling a.u.b.
*** 015/1101/10938 ***

vervaldag
CONTANT TE BETALEN

De klant verklaart uitdrukkelijk kennis genomen te hebben en akkoord te gaan met onze algemene voorwaarden vermeld op de keerzijde van dit document.

Flex Automotive
Wim Janzen

Achterweg 94
4171 BD Herwijnen
Tel. 06-24198007

w.janzen@flexautomotive.nl
www.flexautomotive.nl

[redacted]

Herwijnen, 26 november 2016

Factuurnummer: 2016543
Debiteurnummer: 1675

Specificatie: **Kenteken 1 JSL 755**

Code	Aantal	Omschrijving		Prijs
ac4112	1	vloermatset	€	66,03
RM4750	1	REMBEKRACHTIGER ORG. LOCKHEED - STANDAARD.	€	294,00
	1	remleiding met nippels	€	11,20
RM4770	1	FLEX.BEKR.SLANG - ALLE BEKR.MODELLEN	€	8,91

Sub-totaal		€	380,14
Bij: Omzetbelas	BTW verlegd: BTW nr. BE 0821.016.908	0% €	-
Verzendkosten			
Totaal		€	380,14

Wij verzoeken u het **te betalen bedrag binnen 7 dagen** na de factuurdatum over te willen maken op onderstaande bankrekening onder vermelding van het factuur- en debiteurnummer.

Bankgegevens; IBAN: NL43 INGB 0683 3968 38 BIC: INGBNL2A

BTW-nr: NL 8084.07.569.B.01

Authorized Imported Car, LLC.
Trading as Don's Jaguar Service
Flemington, NJ - 908-788-1982

JAGUAR


CUSTOMER	VEHICLE	WORK ORDER
[redacted]	1966 Austin-Healey	WO # : 1754
	Plate : 1084QQ	Date : 07/28/2005
	Odomtr: 77,112	PO # :
	V.I.N.:	REG # :
	Unit #:	Tech. : JAGSHOP/JAGSHOP
H#:908 788-7866 B#:	Engine:	

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labour	Total	C
	10.00	SERVICE VEHICLE AS REQUIRED: 1-CHECK OVER VEHICLE AND REPORT TO CUSTOMER. 2-REMOVE OLD ROTTEN EXHAUST SYSTEM USING CARE NOT TO BREAK EXHAUST MANIFOLDS. ALL HANGERS AND BRACKETS RUSTED BEYOND REUSE. INSTALL COMPLETE NEW STAINLESS STEEL EXHAUST SYSTEM WITH ALL NEW HANGERS, BRACKETS, AND MOUNTS. **REQUIRED REPLACEMENT OF 2 RUSTED MANIFOLD STUDS THAT BROKE DURING DISASSEMBLY. 3-REMOVE, CLEAN, AND OVERHAUL TWIN SU CARBS, REFIT TO VEHICLE, AND TUNE ENGINE TO SPECS. **REPLACED BRASS FLOATS DUE TO LEAKAGE AND COROSSION. 4-RECTIFY OIL LEAK AT OIL FILTER ADAPTER HOUSING.			850.00	850.00	
1.00		EXHAUST SYS, AH3000 STAINLESS	709.29	709.29		709.29	
1.00		FITTING KIT - CENTER EXHAUST	69.72	69.72		69.72	
1.00		FITTING KIT - REAR EXHAUST AH	66.69	66.69		66.69	
1.00		FITTING KIT - FRONT EXHAUST AH	57.78	57.78		57.78	
1.00		CARBURETTOR MASTER O/H KIT	180.44	180.44		180.44	
2.00		FLOAT, CARBURETTOR, BRASS	27.14	54.28		54.28	
		UPS SHIPPING/FREIGHT				45.00	
		**********					

We are not responsible for loss or damage to cars or articles left in cars in case of fire, flood, theft, or any other cause beyond our control.

I hereby authorize the above repair work to be done along with the necessary materials, and hereby grant you and/or your employees permission to operate my vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. All parts removed are discarded unless specified.

Sub Tot.	1,138.20	850.00	2,033.20
		STX	121.99
			0.00
		Deductible	0.00
		Total	2,155.19
		Amt. Paid	0.00
		Amt. Owing	2,155.19



CUSTOMER	VEHICLE	WORK ORDER
[redacted]	1966 Austin-Healey	WO # : 1754
	Plate : 1084QQ	Date : 07/28/2005
	Odomtr: 77,112	PO # :
	V.I.N.:	REG # :
	Unit #:	Tech. : JAGSHOP/JAGSHOP
H#:908 788-7866 B#:	Engine:	

Qty	Hrs.	Description	Parts Ea.	Tot.Parts	Labour	Total	C
		VEHICLE NEEDS: TIRES, BRAKES					
		HOOD LATCH SCREWS					
		IGNITION SWITCH LOOSE.					
		**********					
		CUSTOMER HAS BEEN ADVISED NOT					
		TO DRIVE CAR DUE TO TIRES AND					
		BRAKES BEING DANGEROUS.					

Copyright Lankar Systems Inc. JBMS 6.0 2005

Don`s Jaguar Service
22 Junction Road Flemington, NJ 08822
Tel.#: (908) 788-1982 FAX: (908) 788-3297

Check us out at WWW.JAGUARSVC.COM or WWW.LANDROVERSVC.COM

Ask about our Warranty Protection Plans for your vehicle. We can provide comprehensive coverage for your vehicle up to 48 Months/Unlimited Miles...

Celebrating 25 Years of British Car Repair - Don's Jaguar Service 1980-2005

PAID BY:...

We are not responsible for loss or damage to cars or articles left in case in case of fire, flood, theft, or any other cause beyond our control.

I hereby authorize the above repair work to be done along with the necessary materials, and hereby grant you and/or your employees permission to operate my vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on the above vehicle to secure the amount of repairs thereto. All parts removed are discarded unless specified.

Sub Tot.	1,138.20	850.00	2,033.20
		STX	121.99
			0.00
		Deductible	0.00
		Total	2,155.19
		Amt. Paid	0.00
		Amt. Owing	2,155.19



MOSS MOTORS, LTD.
440 RUTHERFORD STREET
GOLETA, CA 93117
800-235-6954

786246

[redacted]

908-627-7450

RETURNS - Please see the back of this invoice.
CORE CHARGES - Any core charge shown on this invoice will be refunded upon receipt of a complete, rebuildable core and a copy of this invoice.

CUSTOMER #	P.O. #	BACKORDERS	SOLD BY	SHIP VIA	DATE	INVOICE
02868	*LV		28 FRANK EXT 3224	UPS GRD	11/14/97	956510

RD	SHIP	B/O	ORDERED #	STOCKING #	DESCRIPTIC
HIPPED FROM WH 1, GOLETA, CALIFORNIA					
1	1	0	331-320	331-320	HEATER CONTROL CABLE
1	1	0	PIK-LV	PIK-LV	PIK TO LISA RETURN PR
1	1	0	RET-CDT	RET-CDT	APPLY CREDIT FROM RET
			CM #C69373		
			CREDIT INCLUDES RETURN FREIGHT COSTS.		
			$3.67 CASH REFUND INCLUDED WITH ORIGINAL SHIPMENT.		

PARTS TOTAL
10% ORDER DISCOUNT
SUBTOTAL
TAX
TOTAL
CRD:RETURN
OWING

moss
Moss Motors, Ltd.
P.O. Box 847
Goleta, California 93116

Account No. 302868

Dear Customer:
In order to save you having to pay COD fees, we ask that you remit the small balance of

$ 2.72

Thank You.

PAID
NOV 1[illegible] 1997
MOSS MOTORS LTD.

SEE US ON THE WEB! WWW.MOSSMOTORS.COM

MPORTANT ABBREVIATIONS

NYA- Not Currently Available - It may be available in the future.
NWA- Notify When Available - Not currently available, but we will to notify you when it is.
NLS-No Longer Supplied - Not available, and we do not plan to manufacture.

LONG MOTOR CORPORATION
14600 WEST 107TH STREET, LENEXA, KS 66215
800-255-0088 ORDERS-CATALOG REQUESTS-STATUS
913-541-8500 WORLDWIDE ORDERS
913-599-3299 FAX ORDERS
913-541-0880 KANSAS CITY AREA

LONG MOTOR CORPORATION

ORDER # M96003
DATE 04/05/96

Sold To: 908-627-7450

Ship To:

COR A 08559

[redacted]

08559

ORDER #	ORDER DATE	CATLG	CAR	PAYMENT CODE	CHARGE CARD #	CHARGE NAME
M96003	02/29/96	WG	15 AH 30067	VISA	Charged to VISA	ANTHONY W CORDASCO

QUANTITY	PART #	DESCRIPTION	PRICE	AMOUNT
	0-108	BUFFER-TRUNK LID 3 REQ	SHIPPED	
	2-304	RADIATOR CAP	SHIPPED	
	7-795	FLUID RESERVOIR	SHIPPED	
1	8-201	DISTRIBUTOR CONDENSER	1.91	1.91
2	8-220	DISTRIBUTOR POINT SET 1 REQ	1.95	3.90
	8-241	DISTRIBUTOR ROTOR	SHIPPED	
	9-265	STONE GUARD SET-CHRME-7" ROUND	SHIPPED	
1	9-810	PEDAL PAD SET B/C	3.95	3.95
	9-1049	RUBBER BUFFER A/R	SHIPPED	
	9-9306	SEAL-DOOR WAIST LH	SHIPPED	
	9-9307	SEAL-DOOR WAIST RH	SHIPPED	
	9-9705	WIPER BLADE A/R	SHIPPED	
	14-058	DAMPER OIL-CARB 4.2 OZ	SHIPPED	
	9-1310	RUBBER FLOOR MATS-AH LOGO	BACKORD	

BACKORD - BACKORDERED, WILL SHIP WHEN AVAILABLE
TOS - TEMPORARILY OUT OF STOCK, CANCELLED, PLEASE REORDER IN 3-4 WEEKS.
TBA - TO BE ANNOUNCED (AVAILABILITY), PART HAS BEEN CANCELLED FROM ORDER. CHECK AVAILABILITY AT A FUTURE DATE.
NLA - NO LONGER AVAILABLE, STOCK DEPLETED OR NO MANUFACTURER.

NOTES: M96003
SHIP ALLOCATED PARTS

PARTS	9.76
DELIVERY & HANDLING	
CRATING	
CORES	
C.O.D.	
SAME DAY	
STATE TAX	
CREDIT	
TOTAL	9.76

THIS IS A PARTIAL SHIPMENT OF YOUR ORDER

VICTORIA BRITISH LTD

LMC TRUCK

SEE REVERSE FOR RETURN INSTRUCTIONS.

IF THIS IS A CHARGE ORDER THIS IS THE ONLY RECEIPT YOU WILL RECEIVE.

PULLED BY 48 4/5 CHECKED BY 72 PACKED BY 35 4/5

Customer Copy

LONG MOTOR CORPORATION
14600 WEST 107TH STREET, LENEXA, KS 66215
800-285-0088 ORDERS-CATALOG REQUESTS-STATUS
913-541-8500 WORLDWIDE ORDERS
913-599-3299 FAX ORDERS
913-541-0680 KANSAS CITY AREA

LONG MOTOR CORPORATION

ORDER # M96003
DATE 02/29/96

Sold To: 908-627-7450

COR A 08559

[redacted]

Ship To:

08559

ORDER #	ORDER DATE	CATLG	CAR	PAYMENT CODE	CHARGE CARD #	CHARGE NAME
M96003	02/29/96	WS 15	AH 30067	VISA	Charged to VISA	ANTHONY W CORDASCO

QUANTITY	PART #	DESCRIPTION	PRICE	AMOUNT
3	0-108	BUFFER-TRUNK LID 3 REQ	0.74	2.22
1	2-304	RADIATOR CAP	3.95	3.95
1	7-795	FLUID RESERVOIR	64.95	64.95
	8-201	DISTRIBUTOR CONDENSER	BACKORD	
	8-220	DISTRIBUTOR POINT SET 1 REQ	BACKORD	
1	8-241	DISTRIBUTOR ROTOR	1.95	1.95
1	9-265	STONE GUARD SET-CHRME-7" ROUND	12.95	12.95
	9-810	PEDAL PAD SET B/C	BACKORD	
2	9-1049	RUBBER BUFFER A/R	0.74	1.48
1	9-9306	SEAL-DOOR WAIST LH	4.95	4.95
1	9-9307	SEAL-DOOR WAIST RH	4.95	4.95
2	9-9705	WIPER BLADE A/R	7.76	15.52
1	14-058	DAMPER OIL-CARB 4.2 OZ	6.20	6.20
	9-1310	RUBBER FLOOR MATS-AH LOGO	BACKORD	

BACKORD - BACKORDERED, WILL SHIP WHEN AVAILABLE
TOS - TEMPORARILY OUT OF STOCK, CANCELLED, PLEASE REORDER IN 3-4 WEEKS.
TBA - TO BE ANNOUNCED (AVAILABILITY), PART HAS BEEN CANCELLED FROM ORDER. CHECK AVAILABILITY AT A FUTURE DATE.
NLA - NO LONGER AVAILABLE, STOCK DEPLETED OR NO MANUFACTURER.

NOTES: M96003

PARTS	119.12
DELIVERY & HANDLING	15.75
CRATING	
CORES	
C.O.D.	
SAME DAY	
STATE TAX	
CREDIT	
TOTAL	134.87

THIS IS A PARTIAL SHIPMENT OF YOUR ORDER

VICTORIA BRITISH LTD

LMC TRUCK

SEE REVERSE FOR RETURN INSTRUCTIONS.

IF THIS IS A CHARGE ORDER THIS IS THE ONLY RECEIPT YOU WILL RECEIVE.

PULLED BY 37 1/2 CHECKED BY PACKED BY

Customer Copy

Pashouder-Ban
MARLOG CAR HANDLING B.V.

MARLOG CAR HANDLING B.V.

Factuurnr.: **2168210**
Fact.dat: 26-10-2016
Dossiernr.: 201602606/43751
KlantNr: 1625751378
Uw BTWnr:

[redacted]

FACTUUR

Pol: NEW YORK MV.:: MAERSK OHIO VOY 640E ETA: 22-10-2016
Pod: ROTTERDAM
Re: Container: XINU 800246-4 (40'HC) B/L: NYC0072240

VAN : ROOSENDAAL NAAR: DEURLE
BETR: 1 CAR(S) 1965 AUSTIN HEALEY MKIII VIN: HBJ8L31332. 676 Kgs
8,75 Cbm

Ref.: EO-0023007

Omschr.	EUR	Bedrag
Afhandelingskosten loods Roosendaal		379,50
Administratiekosten		55,00
Ecotax		39,50
Inklaringsdocumentatie		75,00
Extra terminal handling charges		36,50
BTW bij invoer 6%		1.116,60
	Totaal EUR	1.702,10

BETAALD
€1300 Euro
Cash pin

Per direct te betalen

Smoorstraat 24, 4705 AA Roosendaal
Rabobank Klundert 12.60.26.572, I-ban NL03RABO0126026572, Swift RABONL2U, VAT NL 00.62.23.527 B 01, K.v.K. Flevoland 20038562
Tel: +31(0)-165-305060, Fax: +31(0)-165-305066, Internet: www.marlog-car-handling.eu

Algemene condities: Met betrekking tot al onze expeditie-werkzaamheden is van toepassing de laatste versie van de Nederlandse EXPEDITIE-voorwaarden zoals gedeponeerd ter griffie van de Arrondissementsrechtbank te Rotterdam. Met betrekking tot al onze Physical Distribution-werkzaamheden is van toepassing de laatste versie van de Physical Distribution-Voorwaarden 1996 zoals gedeponeerd ter griffie van de Arrondissementsrechtbank te Rottedam. Op verzoek worden copieën van de voorwaarden u kosteloos toegezonden.
General conditions: To all our forwarding activities the latest version of the Dutch Forwarding Conditions (FENEX conditions) apply, as registered at the District Court of Rotterdam. To all our Physical Distribution-activities, the latest version of the