July 75 Roof lining part ? placed by self
Aug 75 Corolised hide seats screen surround etc.
" 75 Door handles made operational both sides new cups found.
Winder (windows) mechanism greased & o/hauled
Polythene sheeting stuck to back of door panels - door seals
Replaced. New Rear brake shoes.

ENGINE RECON 63000 miles Aug 76.

New Rings to all pistons, chrome top, special oil control
New (2) liners No's 4 & 5 from front.
Head decarbed valve clearances done by specialist firm
(3) New timing chains to camshafts water pump & oil pump
New " " tensioner.
New core plugs to head
New Hoses.
New top & bottom gasket sets

Aug 76 Breather turned new camshaft drive plug aluminium.

62.800 miles 4 New Tyres

Engine removed for decoking 70.120 New main Bearings. Big ends
Checked using micrometer found to be
Perfect. New engine mountings

71.636 New N.G.K plugs fitted B7HS - Good heat
Range - smooth from lowens in traffic up to
high speeds.

62.010 New Clutch - Driven plate - pressure plate
assembly - thrust bearing.

20/6/80. New Bonnet hinges, completely
Rebuilt front section to eliminate
Corosion.

" Front end of chassis sand blasted
Resprayed
New Sills o/s and N/s

2/81. Complete body respray removing
all glass possible 5 coats primer
etc 7/8 final coats colour

2/83 Rebuild & new brake calipers
etc See Accounts W.T. Akeed & Co

April 90. Retrim - Connolly hide - new carpets &
Roof lining

June 91. New window Rubber to rear window.