McCONECHY'S AUTOFITNESS REPORT

No visible defects apparent ✓
Needs attention (see below*) X
Requires immediate replacement or repair XX
Items not checked O

DATE _____

START TIME _____ FINISH TIME _____

BRANCH NO. 20

NAME [redacted]

CONTACT TEL. No. [redacted]

ADDRESS. _____

6 POSTCODE [redacted]

REG. No. L80 LTT2 MILEAGE _____

MAKE Chrysler MODEL Viper

DUE DATE OF MOT _____

DATE OF LAST SERVICE _____

DATE CHANGE OF CAMBELT _____

TYRES

5 mm	xx mm	4 mm	6 mm	— mm
DRIVERS SIDE FRONT	DRIVERS SIDE REAR	PASSENGER SIDE FRONT	PASSENGER SIDE REAR	SPARE

AIR PRESSURE READING 35 FRONT (BAR) 35 REAR (BAR)

/ CUTS & BULGES / ABNORMAL WEAR PATTERN

TORQUE SETTINGS

Nm	120 Nm	Nm	Nm
DRIVERS SIDE FRONT	DRIVERS SIDE REAR	PASSENGER SIDE FRONT	PASSENGER SIDE REAR
ft/lbs	ft/lbs	ft/lbs	ft/lbs

CHECKED BY VT / VT

EXHAUST

O EXHAUST CONDITION	O CLAMPS, BRACKETS, GASKETS
O MANIFOLD STUD CONDITIONS	O CATALYTIC CONVERTER (VISUAL CHECK ONLY)

BRAKES

ABS: YES ☐ NO ☐

O PADS	O SHOES
O DISC CONDITION	O DRUMS
O DISC THICKNESS (mm)	O WHEEL CYLINDERS
O FLUID LEVEL	O PIPES & HOSES
O HANDBRAKE ACTION	

SUSPENSION & STEERING

O ALIGNMENT	O TRACK CONTROL ARM BUSHES
O TRACK ROD ENDS	O SHOCK ABSORBER CONDITION
O GAITORS	

LUBRICATION & COOLING

O ENGINE OIL LEVEL	O WATER LEVEL
O POWER STEERING FLUID LEVEL	O WASHER BOTTLE
O HOSES	

ELECTRICS

O LIGHTS/ INDICATORS	O DRIVE BELTS
O WIPER CONDITION	O HORN
O BATTERY	

No. 176582

WORK CARRIED OUT

OSR 335/35/17 Pirelli
E461

WE RECOMMEND ATTENTION TO THE FOLLOWING ITEMS

FITTER'S NAME: VT

I have been made aware of the recommendations listed above.
Do you wish a fitness check carried out on your car? Y ☐ N ☐

CUSTOMER'S SIGNATURE: _____

This report summarises the preliminary visual checks on your vehicle. It does not attempt to conduct a detailed inspection or examination of the vehicle or the specified component parts. In our opinion, if items require immediate replacement or repair, failure to do so may make your vehicle unroadworthy and thus likely to cause accident or injury.