COLBROOK
Rolls Royce and Bentley
SPECIALISTS

24 High Street
Stilton
Peterborough
PE7 3RA
Tel: (01733) 243737
Fax: (01733) 243738
www.colbrookspecialists.co.uk

6 July 2016

Invoice No: 23568

[redacted]

Work completed on:

Rolls-Royce Silver Spur

Registration Number: BIG 37
Chassis No: VCX59920
Mileage: 92783

Remove all wheels to balance and re-fit.	1.00 hour	£	60.00
Replace broken fuse box cover catch.	0.25 hour	£	15.00

Parts:

Fuse box lid catch	£	4.39
Sub total	£	79.39
VAT	£	15.88
Sub total	£	95.27
MOT	£	54.00
Total	£	149.27

If you pay by Credit Card the total amount will be: £ 152.26

There is a 2% surcharge on all credit card payments. Debit cards will incur no charge.

Goods shall remain the property of the seller until the funds are cleared

COLBROOK
Rolls Royce and Bentley
SPECIALISTS

24 High Street
Stilton
Peterborough
PE7 3RA
Tel: (01733) 243737
Fax: (01733) 243738
www.colbrookspecialists.co.uk

29 April 2016

Invoice No: 23460

[redacted]

Pd. 20/5/16
11.02.

Registration Number: R947 JBA
Chassis No: VCX59920
Mileage: 91000

Renew starter and engine management relays and check starter motor connections.	0.50 hours	£	30.00
Remove euro plates and metal plinth to fit number plates BIG 37	0.50 hours	£	30.00
Remove grille to fit UK spec front number plate surround and new plate	2.00 hours	£	120.00
Clean contacts in both front heated seat switches and test	0.25 hours	£	15.00
Check vibration and balance all wheels	0.50 hours	£	30.00
Fit new fuel flap rubber stops	0.20 hours	£	12.00
Fit battery charger lead to terminals.	0.10 hours	£	6.00
Remove all door panels and replace all eight speakers test and refit panels	5.00 hours	£	300.00
Flat and machine polish vehicle all over hand glaze and wax		£	340.00
Parts:			
2 Relays	@ £ 21.90 each	£	43.80
Engine management relay		£	10.15
Battery adapter charge lead		£	7.99
2 Fuel flap stops	@ £ 3.30 each	£	6.60
Number plate plinth		£	255.00
Number plate front		£	14.00
Number plates – large rear, standard front		£	28.00
10 Number plate tapes	@ £ 0.24 each	£	2.40
4 Door Speakers		£	120.00
4 Door tweeter speakers		£	100.00
Polishing compound		£	8.46
1.50 Litres Castrol Magnatec engine oil	@ £ 6.25 per litre	£	9.38
Sub total		£	1488.78
VAT		£	297.76
Total		£	1786.54

If you pay by Credit Card the total amount will be: £ 1822.27
From 1 March 2011 there will be a 2% surcharge on all credit card payments. Debit cards will incur no charge.

Goods shall remain the property of the seller until the funds are cleared

VAT Reg. No. 425 5082 65

Pd. 10.3.16.
wedding Cars

COLBROOK
Rolls Royce and Bentley
SPECIALISTS

24 High Street
Stilton
Peterborough
PE7 3RA
Tel: (01733) 243737
Fax: (01733) 243738
www.colbrookspecialists.co.uk

24 February 2016

Invoice No: 23362

[redacted]

90 875 miles

Work completed on:

Rolls-Royce Silver Spur

Registration Number: R947 JBA
Chassis No: VCX59220
Mileage: 146250

Check over.	2.00 hours	£	120.00
Adjust hand brake.	0.50 hour	£	30.00
Fit kmh/mph speedo and change dip to miles.	2.00 hours	£	120.00
Re-seal both leaking brake pumps.	4.00 hours	£	240.00
Replace wiper blades.	0.25 hour	£	15.00
Re-glue drivers side rear door seal.	0.10 hour	£	6.00
Straighten steering wheel by adjusting track rods.	1.50 hours	£	90.00
Lubricate sticking drivers vanity mirror light switch.	0.10 hour	£	6.00
Program new alarm remote to vehicle.	0.50 hour	£	30.00

Parts:

Speedo kph/mph – used		£	150.00
4 Brake pump 'o' rings – large	@ £ 3.29 each	£	13.16
2 Brake pump 'o' rings – small	@ £ 1.99 each	£	3.98
2 Wiper blades	@ £ 16.96 each	£	33.92
4 Split pins	@ £ .05 each	£	.20
Alarm remote		£	180.00
Wheel trim tool		£	38.15
1.00 Litre Mineral oil		£	15.76
Sub total		£	1092.17
VAT		£	218.43
Total		£	1310.60

N.B. All speakers require replacing.
No rear fog light switch fitted. Will require for MOT.
Petrol flap rubber requires replacing.

If you pay by Credit Card the total amount will be: £ 1336.81
There is a 2% surcharge on all credit card payments. Debit cards will incur no charge.

Goods shall remain the property of the seller until the funds are cleared

Bowling-Ryan Ltd

Stoneclough Road,
Kearsley,
Bolton,
BL4 8NF.
01204 700300

RECEIVED
26 AUG 2015

NOMINAL

Service & repair of Rolls-Royce & Bentley Motor Cars
Specialists in Quality & High performance Motor Cars

[redacted]

Rolls paid OK to pay ✓

INVOICE

Invoice No.	**1037917**
Account No.	HAYW01
Order Ref.	
Invoice Date.	21/08/2015
Payment Method.	Account
Date of Work.	21/08/2015

Registration	Make & Model	Chassis Number	Engine CC	Mileage
R947JBA	ROLLS ROYCE SILVER	SCAZN20C5VCX59920	6740	

Labour Description	Qty			Price
TO SUPPLY KEY				
TO REMOVE RADIATOR AND REPLACE WITH S/X				
TO REMOVE JAP RADIO AND REPLACE WITH NEW				
TO TIGHTEN ENGINE SUMP				
TO CARRY OUT GEARBOX SERVICE, THEN DRAIN AND REFIL GEARBOX				
SUMP TWICE HAVING BEEN DRIVEN	8			392.00
			Labour Sub Total	**392.00**

Parts Description	Part No	Qty	Unit Price		Price
SPARK PLUGS	BKR4EVVX	8	8.98		71.84
HEADLIGHT CONVERTORS	92160	1	4.02		4.02
RADIATOR SX	UE73201SXR	1	395.00		395.00
ANTIFREEZE	ANTETHB	6	4.89		29.34
	CARRAIGE	1	13.50		13.50
KEY WITH ENCODER UNCUT	UV10353PD	1	80.43		80.43
RADIO BLUETOOTH,CD,USB	ALPINE	1	149.00		149.00
GEARBOX FILTER 93>	GM8684221	1	69.77	Less 25%	52.33
GEARBOX GASKET 93>	GM8677009	1	61.25	Less 80%	12.25
DEXTRON III	CASTROL 1740	14	5.89		82.46
				Parts Sub Total	**890.17**

Net Subtotal	1,282.17
VAT at 20%	256.44
Total Due	**1,538.61**

R.R. & B SERVICES

Rolls-Royce and Bentley Specialists

Office: 69 Coleridge Road, Romford, Essex RM3 7BD

☎01708 346196 📱 07941 826364

WORKSHOP: By appointment only

GOODMAYES MOTOR SALES LTD — 86550 miles

Rolls Royce SILVER SPUR VCX 59920 139,290 KMS.

Date: 14th JULY 2015

To

CARRY OUT ANNUAL SERVICE, RENEW DAMPER RUBBERS, TIDY UP WIRING — COMPLETE £275 = 00

SUPPLY + FIT NEW OIL PRESSURE TRANSMITTER SWITCH — MAT £56 = 00, LAB £30 = 00

STRIP N/S/R DOOR TRIM + REMOVE FRAME CLEAN OFF EXCESS GLASS. SUPPLY + FIT NEW 1/4 WINDOW GLASS TO FRAME, REFIT SAME — MAT £110 = 00, LAB £120 = 00

SUPPLY + FIT NEW FRONT SUB-FRAME DAMPER — MAT £95 = 00, LAB 60 = 00

REMOVE BOOT LOCK + REMOVE BARREL, REMOVE BROKEN CATCH. SUPPLY + FIT NEW CATCH, REASSEMBLE + REFIT — COMPLETE £70 = 0

REMOVE REAR ROAD WHEELS, FREE OFF HANDBRAKE CABLES, ADJUST AS REQUIRED — COMPLETE £90 = 0

STRIP N/S/R DOOR TRIM, CHECK FOR WINDOW FAILURE. SUPPLY + FIT 2 NEW RELAYS, REFIT DOOR TRIM ECT — COMPLETE £80 = 0

SUPPLY + FIT 2 NEW GAS SPHERES TO ACCUMULATORS, BLEED, TOP UP RESERVOIRS — COMPLETE £150 = 0

SUB. TOTAL £1,136 = 00

SPARE WHEEL + TYRE 50 = 00

TOTAL £1,186 = 00


*** CUSTOMER COPY ***
COLBROOK SPECIALISTS
24 HIGH STREET
PE7 3RA
THANK YOU
17:24:31 15/11/16
Receipt 1475
MID: ***82442 TID: ****8986
Visa
**********6853
A0000000031010 Issue 04
SALE CHIP
£1,140.29
PIN VERIFIED
APPROVED
AUTH CODE: 002588
7B85E9EBA2A31765
S:1 TC
Please debit my account
with the total amount
PLEASE RETAIN RECEIPT

24 High Street
Stilton
Peterborough
PE7 3RA
Tel: (01733) 243737
Fax: (01733) 243738
www.colbrookspecialists.co.uk

Invoice No: 23743

Work completed on:

Rolls-Royce Silver Spur

Registration Number: R947 JBA
Chassis No: VCX59920
Mileage: 93260 m

Road test for brake judder .Skim rear brake discs, re-face rear brake pads and refit re-test.	3.00 hours	£ 180.00
Replace worn front brake discs and pads.	5.00 hours	£ 300.00
Balance all wheels whilst removed.	0.50 hours	£ 30.00
Reset milometer to read in kilometres.	0.25 hour	£ 15.00

Parts:

2 Front brake discs	@ £ 127.45 each	£ 254.90
Front brake pads		£ 127.29
2 Cable ties	@ £ 0.05 each	£ 0.10
2 Front hub split pins	@ £ 2.16 each	£ 4.32
1 week storage from 08/11 to 15/11/16	@ £ 20.00 week	£ 20.00

Sub total	£ 931.61
VAT	£ 186.32
Total	£ 1117.93

Paid with thanks

If you pay by Credit Card the total amount will be: £ 1140.29

There is a 2% surcharge on all credit card payments. Debit cards will incur no charge.

Goods shall remain the property of the seller until the funds are cleared

VAT Reg. No. 425 5082 65